

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIP  
(Other instruction re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NO. <b>NM-0557837</b>
2. NAME OF OPERATOR <b>AMOCO PRODUCTION COMPANY</b>	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR <b>BOX 367, ANDREWS, TEXAS 79714</b>	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <b>1980' FSL x 1980' FWL Sec. 26 (Unit K, NE 1/4 S1/4)</b>	8. FARM OR LEASE NAME <b>MIDWEST F FED.</b>
14. PERMIT NO.	9. WELL NO. <b>1</b>
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <b>4312' DF</b>	10. FIELD AND POOL, OR WILDCAT <b>VADA-PENN</b>
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <b>26-9-33 NMPM</b>
	12. COUNTY OR PARISH <b>LEA</b>
	13. STATE <b>NM</b>

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*


(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

In an effort to restore well to production propose to set a CIBP @ 9600' x Cap w/ 10' Cement to isolate Bough C puffs 9653-63'. Perforate add'l interval 9476-86' w/ 2JSPF (Three Brothers) Acidize w/ 3000 gal 15% NE HCL and evaluate. Restore to production.

18. I hereby certify that the foregoing is true and correct

SIGNED



TITLE

ADMINISTRATIVE ASSISTANT

DATE

MAY 19 1975

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:


TITLE

DATE

014 USGS-40885

1-DIV  
1-SOSP  
1-RRY

\*See Instructions on Reverse Side

  
MAY 21 1975