

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-098591 (CASW-544)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR
BOX 68, HOBBES, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660 FNLx 1980 FEL Sec. 34 (Unit B NW 1/4 NE 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4236' R.D.B.

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

MOLEEN Federal Oil COM

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

VADA - Penn

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

34-9-34 NM PM

12. COUNTY OR PARISH 13. STATE

LEA N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Physical abandonment of well concluded 10-22-70.
P+A as follows:

loaded hole w/ mud.

Spotted 35 qt. cement plug @ 8224'

shot 5 1/2" @ 5100, 4940' and pulled from 4273'. Spotted 35 qt
cement plug (@ 4320') in & out of stub.

Spot 35 qt in + out of 8 5/8" CSA 4061.

shot & pulled 8 5/8" from 1198'. Spotted 25 sx (@ 1240') in
& out of stub.

Spot 25 qt. in + out of 13 3/8" CSA 401

Spot 10 qt @ surface & erect P+A marker.

Final cleanup shall be made and ground restored to
contour.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Sup

DATE

10-30-70

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

044-USGS-H

1- AC Jr

2- WF Spencer

1- SUSP

1- RRY

1- SUPERIOR-MIDLAND

1- " -HOUSTON

*See Instructions on Reverse Side

RECEIVED

JUN 22 197

OIL CONSERVATION COMM
HOBBS, N. M.