

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator BTA Oil Producers	8. Farm or Lease Name Ray 700 Ltd.
3. Address of Operator 104 South Pecos, Midland, Texas 79701	9. Well No. 2
4. Location of Well UNIT LETTER "H" 1980 FEET FROM THE North LINE AND 510 FEET FROM THE East LINE, SECTION 15 TOWNSHIP 9-S RANGE 35-E NMPM.	10. Field and Pool, or Wildcat Vada-Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4140 GL, 4152 KB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:	
REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged & Abandoned as Follows:

Set CIBP @ 9700' w/2 sx cmt on top  
Cut & pulled 5½" csg @ 6305'  
25 sx @ 6305' (5½" stub)  
25 sx @ 5474' (Glorietta)  
25 sx @ 4076' (8-5/8" shoe)  
Cut & pulled 8-5/8" csg @ 1186'  
25 sx @ 1186' (8-5/8" stub)  
25 sx @ 375' (12-3/4" shoe)  
10 sx @ surface  
Installed dry hole marker per NMOCC regulations  
Plugged & abandoned 1-6-72

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. D. Payne TITLE Production Clerk DATE 1/18/72

APPROVED BY Nathan E. Clegg TITLE OIL & GAS INSPECTOR DATE JUN 7 1972

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JAN 2 1972

OIL CONSERVATION COMM.  
HIDES, D. L.