

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPY
(Other instruction:
verse side)TE*
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NEW MEXICO 198 NM-918

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME SW-558
2. NAME OF OPERATOR MIDWEST OIL CORPORATION <i>Associated Co</i>	8. FARM OR LEASE NAME FEDERAL H
3. ADDRESS OF OPERATOR c/o Hobbs Pipe & Supply, Box 2010, Hobbs, N. M. 88240	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 1980' FWL	10. FIELD AND POOL, OR WILDCAT Vada Penn
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 18-9-35
	12. COUNTY OR PARISH Lea
	13. STATE N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Spotted a 25 sx plug @ TD to cover existing perforations.
2. Loaded hole w/mud-laden fluids.
3. Recovered production casing of 4,000'.
4. Spotted a 50 sx plug in & out of base of intermediate casing set @ 4046', which was also the stub of the 5-1/2" casing.
5. Shot & recovered 8-5/8" casing from 1000' & spotted a 50 sx plug.
6. Spotted a 50 sx plug in & out of base of 11-3/4" set @ 320'.
7. Spotted a 10 sx top-hole plug & erected a 4" regulation marker.
8. Well was Plugged & Abandoned on 6/28/73.

18. I hereby certify that the foregoing is true and correct

SIGNED

Stanley Siskin

TITLE

Agent

DATE 7/9/73

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY: