NE. XICO OIL CONSERVATION COMMISSIC WELL LUCATION AND ACREAGE DEDICATION PLAT

All distances must be from the outer boundaries of the Section.

									
ROGER C. HANKS				FORD			١,	/ell No.	
Init Letter Section Township		Township	Range County						
В	18	9 South		36 EAST	<u></u>		LE	Α	
Actual Footage Loc 660	feet from the	NORTH line and		1980 fee	t from the	EAST	lir	ne	
Ground Level Elev.	Producing For	mation	Pool					d Acreage:	
4092,91	Bough	· -		lesignated			16		
1. Outline th	e acreage dedica	ted to the subject we	ell by	colored pencil o	r hachure	marks on th	e plat b	elow.	
	nan one lease is nd royalty).	dedicated to the well	l, outl	line each and ide	ntify the o	wnership tl	nereof (l	ooth as to working	
		ifferent ownership is o unitization, force-pooli			have the i	nterests of	all own	ers been consoli-	
Yes	☐ No If an	nswer is "yes;" type o	of cons	solidation			···········		
If answer	is "no," list the	owners and tract desc	riptio	ns which have ac	tually bee	n consolida	ated. (U	se reverse side of	
this form i	f necessary.)								
		ed to the well until all							
torced-poo sion.	ling, or otherwise	or until a non-standare	a unit	, eliminating suc	n interests	s, nas deen	approve	ed by the Commis-	
							CERTIF	CATION	
	İ		•				CERTI	TEATION	
		0	5.	1		I hereby o	ertify the	t the information con-	
	1	•		1980		tained he	rein is tru	e and complete to the	
	1			1		best of m	knowled ر	ge and belief. ^7 /	
	1			‡ 		Köger	<u>, C</u>	Hanks	
	+			-		Name /	land	a Sanders	
	1			1		Position			
	 			l I		Oper Company	<u>ator</u>		
	Norm (Gr	TOURING ELECTION IS	7 0	CEET WOUED		1	r C.	Hanks	
 	NOTE: GROUND ELEVATION			N AMERICAN PETROLEUM			Date		
		ORP. REED "A" NO.		•		Apri	1 27,	1970	
		C. 18, 75, KJOE							
				 		i hernby	certify t	hat the well location	
	I			ĺ		shown on	this plat	was plotted from field	
	1			SINEER &		l .		rveys made by me or	
	 			THE W		1		on, and that the same It to the best of my	
	1			PULL OF THE		knowledge			
 -	+		<u>- 1</u>	- - 676\					
	l		到			Date Survey			
	 			MEXICO A		i		11, 1970	
	i	`		OHN W. WEST				nal E nginee r	
	i .		"	W.		oend√or Loone	Surveyor	, , ,	
	<u> </u>			<u> </u>		10	fry 1	Wast	
0 220 220	100 1000 1000 100	0 2310 2840 2000		500 1000 -		Certificate	No.	676	
0 330 860	190 1320 1650 186	10 231C 2840 2000	. 1	800 1000 B	00 0	L			



RECEIVE

APP 2 5 1970

94 COMM 4 1701 C