

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-6676
7. Unit Agreement Name -
8. Farm or Lease Name Sohio
9. Well No. 1
10. Field and Pool, or Wildcat North Bagley (undes.)
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
SEE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator Read & Stevens
3. Address of Operator P. O. Box 2126, Roswell, New Mexico 88201
4. Location of Well UNIT LETTER K 1980 FEET FROM THE South LINE AND 2087.8 FEET FROM THE West LINE, SECTION 7 TOWNSHIP 11S RANGE 33E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4322.7' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-5-70: Set 25 sx cmt plug @ 9800' to 9722'
" " " " " " 8500' to 8422'
" " " " " " 7340' to 7262'
" " " " " " 5085' to 5007'
" " " " " " 3732' to 3654'
Cut and removed 8 5/8" csg @ 1481'
Set 25 sx cmt plug @ 1519' to 1464'
" " " " " " 403' to 372'
Set 10 sx cmt plug @ 10' to 0'

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>William E. Olsen</i></u>	TITLE <u>Agent</u>	DATE <u>8-6-70</u>
APPROVED BY <u><i>Nathan E. Olegg</i></u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>DEC 22 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		