

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-4243

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER DRY	7. Unit Agreement Name
2. Name of Operator JACK F. GRIMM	8. Farm or Lease Name CHASTE
3. Address of Operator P. O. Box 35, Abilene, Texas	9. Well No. 1
4. Location of Well UNIT LETTER P 660 FEET FROM THE East LINE AND 660 FEET FROM THE South LINE, SECTION 8 TOWNSHIP 11. S RANGE 32. E NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4,400 (est.) GR.	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Commenced drilling 6/27/70.
Plugging operations began & ended 8/10/70.
Total depth 11,281'.
Used 9.3# mud to plug plus cement

Set 3,531' 8 5/8" casing, cemented with 350 sx.
Set 355' 13 3/8" casing with 300 sx.

Set cement plugs at: 11,203-11,281 - 25 #X
8,943-9,020 - 25 #X
8,228-8,363 - 25 #X
6,233-6,330 - 25 #X
4,803-4,880 - 25 #X
~~EXPLOSION PROCEEDING~~
3,441-3,518 - 25 #X
10 sx in top of surface casing

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jack F. Grimm TITLE Operator DATE 10/14/70

APPROVED BY John W. Runyan TITLE Geologist DATE 10/14/70

CONDITIONS OF APPROVAL, IF ANY: