STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

40. 07 COPIES RECEIVES		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR	T	ī

N DIVISIO.

Form C-103 Revised 10-1-78

NO. OF COPIES RECEIVED	JIL CONSERVATIO	
DISTRIBUTION	P. O. BOX 208	
SANTA FE	SANTA FE, NEW ME	
FILE		
U.S.G.S.		
LAND OFFICE		

FILE	7 7 E, 14EW MEXICO 8/301		
U.S.G.S.		5a. Indicate Type of Lease	
LAND OFFICE		State X Fee 5. State Oil & Gas Lease No.	
DPERATOR		K-3774	
SUNDRY NOTICES AND	REPORTS ON WELLS		
USE "APPLICATION FOR PERMIT -" (FOR	DEEPEN ON PLUG BACK TO A DIFFERENT RESERVOIR. M C-101) FOR SUCH PROPOSALS.)		
1. OIL X SAS OTHER-		7. Unit Agreement Name	
2. Name of Operator		8. Farm or Lease Name	
JOHN L. COX		Shell E State	
3, Address of Operator		9. Well No.	
P. O. Box 2217, Midland, Texas 797	(02	1	
	HE North LINE AND 2130 FEET FR	N. Bagley (Penna.)	
**	NASHIP 12-S RANGE 33-E NMF		
15, Elevation	on (Show whether DF, RT, GR, etc.) 4266 GR	12. County Lea	
16. Check Appropriate Box 7	To Indicate Nature of Notice, Report or C	Other Data	
NOTICE OF INTENTION TO:		NT REPORT OF:	
PERFORM REMEDIAL WORK PLUG A	ND ABANDON REMEDIAL WORK	ALTERING CASING	
	COMMENCE DRILLING OPNS. PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT	
	OTHER		
OTHER			
17. Describe Proposed or Completed Operations (Clearly state	all pertinent details, and give pertinent dates, include	ing actimated data of examination and property	
work) SEE RULE 1103.	wit pertinent details, and give pertinent dutes, include	ng estimated date of starting any proposed	
1. Moved in Plugging Rig 6-17-91.			
2. Attempted to set CIBP - Unsuccessf	ul.		
3. Spot 60 sx cement plug @9600-9455'			
4. Spot 30 sx cement plug @9455-9020'			
5. Spot 25 sx cement plug @8446-8108'			
6. Spot 25 sx cement plug @7830-7492'7. Spot 25 sx cement plug @5100-4762'	(Top of Abo @7830').		
8. Spot 50 sx cement plug @4236' (Tag			
Recovered 4189'- 4-1/2" casing (Ca	ged 4020).		
9. Spot 65 sx cement plug @3800' (Tag	ged @3580').		
10. Spot 200 sx cement plug @580' (Tag	ged @202').		
Recovered 537' - 8-5/8" casing (Ca	sing stub @530').		
1. Spot 10 sx cement plug surface-10'			
2. Install Dry Hole Marker. Work Comp	leted 6-26-91.		
.3. Well filled with $9.5\#$ mud laden fl	uid between plugs.		
18. I hereby certify that the information above is true and comp	lete to the best of my knowledge and belief.		
BIGHED Marthe Martinta	Production Mgr.	7/30/91	
12/11/1	OIL & Comment	. nee (5.1991	
APPROVED BY JAMES W. THE	OIL & CATES LIVER ECTOR	DATE STATE	
CONDITIONS OF APPROVAL, IF ANY:			

a lang

AUG 0 I 1991 Hodes Carce