

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR APPLICATION TO OIL OR TO OTHER RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL FOR OIL OR GAS.)		5a. Indicate Type of Lease State ☐ Fee ☒ 5. State Oil & Gas Lease No.
1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER 2. Name of Operator The Maurice L. Brown Co. 3. Address of Operator Suite 200, Sutton Place Bldg., Wichita, Kansas 67202 4. Location of Well UNIT LETTER <u>F</u> <u>1980'</u> FEET FROM THE <u>North</u> LINE AND <u>1980'</u> FEET FROM THE <u>West</u> LINE, SECTION <u>3</u> TOWNSHIP <u>2-S</u> RANGE <u>34-W</u>	7. Unit Agreement Name 8. Form of Lease Name McHulty 7101 JV-D 9. Well No. 2 10. Field and Pool, or Valued Vada Penn	
15. Elevation (Show whether DF, RT, GR, etc.) 4261' GL; 4272' KB		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPHS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Move in and rig up Permian Basin Casing Pullers, Inc.
2. Set cast iron bridge plug in 5 1/2" casing at 9560' (50' above Perforations 9610'-26') Cap with 35' (5 sx.) cement.
3. Load hole with mud laden fluid.
4. Salvage 5 1/2" casing from free point.
5. Spot 35 sx. cement through tubing 50' below casing stub. *{ 100' Plug 50 in / 50 out sub }*
6. Tag top of cement.
7. Spot 35 sx. cement through tubing at 5350' to form 100' plug across top of Glorieta.
8. Spot 35 sx. cement through tubing at 3973' to form 100' plug across 8 5/8" casing seat.
9. Tag top of cement.
10. Spot 35 sx. cement through tubing at 2100' to form 100' plug inside 8 5/8" casing across top of salt section.
11. Salvage 8 5/8" casing. *{ 100' Plug 50 in / 50 out sub }*
12. Spot 70 sx. cement through tubing 50' below 8 5/8" casing stub.
13. Tag top of cement.
14. Spot 70 sx. cement through tubing at 415' to form 100' plug across 12 3/4" casing seat.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>W.M. Dreesbeck</u>	TITLE <u>District Engineer</u>	DATE <u>2-9-78</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u>Geologist</u>	DATE <u>FEB 13 1978</u>

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
FEB 15 1964

FEB 13 1978
OAL COPY TO
BOSTON FIELD

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SAITA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State ☐ Fee ☒
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name McNulty 7101 JV-D
9. Well No. 2
10. Field and Pool, or Wildcat Vada Penn
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO DRILL (Form C-101) FOR SUCH PROPOSALS.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
The Maurice L. Brown Co.

3. Address of Operator
Suite 200, Sutton Place Bldg., Wichita, Kansas 67202

4. Location of Well
UNIT LETTER F 1980' FEET FROM THE North LINE AND 1980' FEET FROM
THE West LINE, SECTION 3 TOWNSHIP 9-S RANGE 34-E NMPM.

15. Elevation (Show whether DF, RT, CR, etc.)
4261' GL; 4272' KB

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPNS. ☐
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOB ☐
OTHER ☐	OTHER ☐
PLUG AND ABANDON ☒	ALTERING CASING ☐
CHANGE PLANS ☐	PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

15. Tag top of cement.
16. Spot 10 sx. cement plug at surface.
17. Erect dry hole marker.
18. Rig down casing pulling rig.
19. Fill cellar and mud pit and level and clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Wm. Groesbeck</u>	TITLE <u>District Engineer</u>	DATE <u>2-9-78</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u>Geologist</u>	DATE <u>FEB 13 1978</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED
FEB 23 1978

U.S. DEPARTMENT OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION
WASHINGTON, D. C.