

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
Novy Oil & Gas, Inc.

3. Address and Telephone No.
125 N. Market St., Suite 1230, Wichita, KS 67202-1712

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
UL "G" 1980' FNL & 1830' FEL
SW/NE Sec. 1, T9S, R34E, Lea County, NM

5. Lease Designation and Serial No.
NM 0202771 A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation
NM 061P 3587 C427

8. Well Name and No.
Government "C" #1

9. API Well No.
30-025-23737

10. Field and Pool, or Exploratory Area
Vada Penn

11. County or Parish, State
Lea, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
☒ Notice of Intent	☐ Abandonment	☐ Change of Plans
☐ Subsequent Report	☒ Recompletion	☐ New Construction
☐ Final Abandonment Notice	☐ Plugging Back	☐ Non-Routine Fracturing
	☐ Casing Repair	☐ Water Shut-Off
	☐ Altering Casing	☐ Conversion to Injection
	☐ Other	☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drill give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- (1) RU rig.
- (2) POOH w/rods & tbg.
- (3) RU Halliburton Wireline. TIH w/4' X 3 1/8" gun loaded 4 SPF & perf 9738-42'. POOH. PU 4' - 3 1/8" perforating gun loaded 4 SPF & perf 9734-38'. POOH. RD Halliburton Wireline.
- (4) PU Halliburton PIP packer set for 1' spacing & TIH. Set pkr. @ 9744'. Load tbg. w/1000 gal. 15% NEFE acid. Pressure tbg. to 500#. Pull up to 9741-42'. Acidize w/100 gal. 15% NEFE acid. Continue to treat w/100 gal. 15% NEFE acid/ft. until all perfs have been treated. Put remaining 200 gal. @ 9730-31'. POOH w/PIP tool.
- (5) PU rebuilt anchor & on/off tool & TIH. Tag btm. & space 3' off btm.
- (6) Run pump & rods & POP.

14. I hereby certify that the foregoing is true and correct

Signed

Michael E. Erbe

Title

Vice President

Date

9/3/97

(This space for Federal or State office use)

Approved by

[Signature]

Title

PETROLEUM ENGINEER

Date

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statement or representations as to any matter within its jurisdiction.

*See instruction on Reverse Side