

U. S. GEOLOGICAL SURVEY  
P. O. Box 1157  
Hobbs, New Mexico 88240      February 27, 1979

Coquina Oil Corporation  
P. O. Drawer 2960  
Midland, TX 79702

Re: Permanent Abandonment

Well: No. 1 Webb Federal

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases".
2. The Hobbs office (telephone (505) 393-3612 is to be notified in sufficient time for a representative to witness all plugging operations.
3. Blowout prevention equipment is required.
4. Surface restoration after abandonment is to be in accordance with the operator-surface owner agreement unless otherwise advised.
5. A 50-sack cement plug should be placed across top of Glorieta.
6. A 50-sack plug should be placed inside 8-5/8" casing in the interval 2200-2350 feet.
7. The cement plugs across the 8-5/8" and 13-3/8" casing shoes must be tagged to assure they are in place and additional cement plug placed if necessary.
8. If 5-1/2" casing cannot be pulled from below 4100 feet, contact USGS office before proceeding further so the need for perforating and cement squeezing can be considered.