SIENED CONTROL ON	Starford TITLE PRODUCTION	ACCNT. 10-11-71
18. I hereby certify that the informati	ion above is trum and complete to the best of my knowledge as	nd belief.
CEVED		
	ME WELL IS ON PUMP WHILE WE TR TO PRODUCE COMMERCIA LY.	Y TO DETERMINE WHETHER TE
& 10% GEL & 8	N-80 & 17# J-55 CSG. SET @ 10, 3# SALT PER SACK. PLUG DOWN 4: MP 30 MIN. HELD OK.	000' W/500 8XS CLASS "C" POZMIX 30 AM 7-13-71. WOC 20 HRS. PRES
SALT POR SACK	32# J-55 SRT @ 3332 W/375 SX . PLUG-DOWN & 12:00 MIDNIGHT S UP W/PUMP 1000# FOR 30 MIN.,	6-13-71. TOP CEMENT 2536'. SI
B. 12 8/4" 34# S 2% CC CIRCULA COLUMN ORLG.	T&C BURFACE CSG., H-40 RANGE 3 TED. PLUG DOWN @ 11:30 AM 6-1 MUD. TOSTED W/PUMP PROSS. TO	3, SET @ 390' W/375 SXS CLASS TH 0-71 SI FOR 18 HRS. WOC 18 HRS. 1000# FOR 30 MIN., HELD OK.
A. SPUD 6-10-71		
	Operations (Clearly state all pertinent details, and give pert	inent dates, including estimated date of starting any proposed
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND	CEMENT JOB
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILL	
	Appropriate Box To Indicate Nature of Notice INTENTION TO:	ce, Report or Other Data SUBSEQUENT REPORT OF:
	15. Elevation (Show whether DF, RT, GR, etc.) 4185 3R.	12. County LEA
THE SOUTH LINE, SEC	TION 1 TOWNSHIP 10-S RANGE 3	32=ENMPM.
, Location of Well UNIT LETTER	660° FEET FROM THE BAST LINE AND 6	10. Field and Pool, or Wildcat WILDCAT
Address of Operator P.O. B	30X- 505, MIDLAND, PRXAS 79701	9. Well No.
	BARNES OIL CO.	8, Form or Lease Name HUDSON -STATE
OIL GAS WELL	OTHER-	
SUND (DO NOT USE THIS FORM FOR F USE "APPLIC	DRY NOTICES AND REPORTS ON WELLS PROPOSALS TO DRILL OR TO DEEPEN OR PLUE BACK TO A DIFFERENT ATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
PERATOR		L=275
AND OFFICE		State X Fee. 5. State Oil & Gas Lease No.
.s.g.s.		Sa. Indicate Type of Lease
ANTA FE	NEW MEXICO OIL CONSERVATION COM	
DISTRIBUTION		Form C-103 Supersedes Old C-102 and C-103

RECEIVED

OCT 13 1971
OIL CONSERVATION COMM