

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLE
(Other instructions
refer to side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

M 14284

6. IF NEAR, ADDRESS OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Coastal States Gas Producing Company		8. FARM OR LEASE NAME Gonsales Federal "31" 1/4	
3. ADDRESS OF OPERATOR P. O. Box 235, Midland, Texas 79701		9. WELL NO. #1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FSL & 660' FEL		10. FIELD AND POOL, OR WILDCAT Flying "M" (San Andres)	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4226' GR	
		12. COUNTY OR PARISH Lea	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☒SHOOTING OR ACIDIZING ☒(Other) ☐

casing

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Rigged up, pulled tubing & packer. Set CIBP @ 8900' w/40' cement on top of plug. Ran free point, cut 5-1/2" csg. with jet cutter @ 4550'. Recovered 4538' 5-1/2" 17# csg. WIH w/2-7/8" tbg. to 4566'. Set 25 sx. plug @ 4566'-4489'. WOC 18 hrs. WIH w/bit. Found top of plug @ 4489'. Press. up on plug w/2000#. Held O.K. POOH. Picked up & ran 143 jts. 5-1/2" 17# csg. Set @ 4489' & cemented w/250 sxs. PD @ 6 p.m. 3-8-73. WOC 18 hrs. Tested csg. to 1000#. Held O.K. WIH and perf. csg. 4239'-42', 59'-61', 64'-70' w/2, 1/2" SPF. Treated perfs. w/3000 gal. acid. Put on pump.

18. I hereby certify that the foregoing is true and correct

SIGNED

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE Dist. Prod. Superintendent

DATE 3-26-73

TITLE

ACCEPTED FOR RECORD

APR 4 1973

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO