Used 3 centralizers at 4106', 4021, & 3978'. On 1/5/72: Tested csg. & B.O.P.with 1000# Press for $\frac{1}{2}$ Loss of pressure.	HR. WITH NO
	HR. WITH NO
Used 3 CENTRALIZERS AT 4100', 4021, & 39/0'.	
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	
WITH 350 SKS. CLASS H CEMENT WITH 2% CA. CL.	
ON 1/4/72, HALLIBURTON CEMENTED 8 5/8" O.D. 32#, 28#	& 24# csg.At 41161
DRILLED !1" HOLE TO 4116'.	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703.	estimated date of starting any proposed
OTHER	
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB OTHER NTERMEDIAT	E CASING X
TEMPORARILY ABANDON COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
NOTICE OF INTENTION TO: SUBSEQUENT PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	REPORT OF:
Check Appropriate Box To Indicate Nature of Notice, Report or Oth	ner Data
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
THE WEST LINE, SECTION 17 TOWNSHIP 9-S RANGE 36-E NMPM.	
UNIT LETTER F . 1980 FEET FROM THE NORTH LINE AND 1980 FEET FROM	VADA PENII
P. O. Box 848, Roswell, New Mexico 88201	10. Field and Pool, or Wildcat
JACK L. MCALLALANA 3. Address of Operator	ANN FEE
2. Name of Operator	8. Farm or Lease Name
OIL GAS OTHER-	7. Unit Agreement Name
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
OPERATOR	5, State Cil & Gas Lease No.
LAND OFFICE	State Fee
FILE	5a. Indicate Type of Lease
DISTRIBUTION NEW MEXICO OIL CONSERVATION COMMISSION	Form C=163 Supersedes Old C=102 and C=103 Effective 1=1-65

CONDITIONS OF APPROVAL, IF ANY: