

SANTA FE PACIFIC #10

11/2 (39) 11,195 drlg lm & sh, 8-3/4" hole, NND. 9.8-45, 5% oil.

SANTA FE PACIFIC #10

11/3 (40) 11,350 drlg lm & sh, 8-3/4" hole, NND. 9.8-44-5% oil.

SANTA FE PACIFIC #10

11/4 (41) 11,518 drlg lm, 8-3/4" hole, NND. 9.8-45-6% oil.

11/6 (43) 11,640 ND lm, 8-3/4" hole, 1 1/2 @ 11,640, 9.7-60-10.0, 6% oil.
while GIH w/ new bit @ 11,640, DP parted 14 stands off bottom, dropped 8-3/4
bit, 25 - 6 1/2 DC's + 17 jts & 20' piece of 4 1/2 DP, est top of fish @ 10,342,
ran 8" OD OS stopped @ 9330, POH w/ OS, ran 8-3/4 bit to 9330, cond mud/5
hrs, then CO to 9550, cont to CO hole.

SANTA FE PACIFIC #10

11/7 (44) 11,640 ND lm, 8-3/4" hole, NND, 9.7-70-10.0, 5% oil.
cond hole & CO to 9600 past 24 hrs.

SANTA FE PACIFIC #10

11/8 (45) 11,640 ND lm 8-3/4" hole, NND. 9.7-55-10.0, 5% oil.
Cond mud at 9600' 9 hrs, POH w/ bit, ran 7-7/8" wash over mill on 1
jt 7-3/8 wash pipe, DC's & DP to 9600, milled thru bridge, ran mill
to 10,070, now cond mud & hole @ 10,070.

SANTA FE PACIFIC #10

11/9 (46) 11,640 ND lm & sh, 8-3/4" hole, 9.8-55-7.0, 6% oil.
CO to 10,347, top of fish, washed over fish to 10,379, POH w/
DP, DC's and WP, ran 7-5/8 OD outside cutter to 10,370, cut
4 1/2 DP, POH, rec 23' piece of 4 1/2 DP, now GIH w/ 8-1/8 OS, B. Sub,
jars, DC's & DP.

SANTA FE PACIFIC #10

11/10 (47) 11,640 ND lm & sh, 8-3/4" hole, 9.8-55-7.0, 6% oil.
ran OS to fish @ 10,370, caught fish, jarred 3 times, OS
slipped off fish, POH, rerun OS w/ 4-3/8 grapples to 10,370,
unable to catch fish, POH, rerun OS different guide - caught
fish, ran free pt indicator, indicated fish stuck at bottom
of OS, rel OS from fish, now POH, prep to wash over fish.

SANTA FE PACIFIC #10

11/11 (48) 11,640 ND lm & sh, 8-3/4" hole, NND, 9.8-55-7.0, 6% oil.
finish POH, ran 12 jts 8-1/8" OD WO pipe & mill to top of
fish @ 10,370, WO fish to 10,716, circ 3 hrs, POH w/ WP, ran
OS to 10,370, caught fish, prep to run free pt indicator.

11/13 (50) 11,640 ND lm & sh, 8-3/4" hole, NND. 9.8-55-8.0, 6% oil.
Homco ran free pt indicator, lost tools in DP, attempted to
fish out tools w/ no success, ran string shot back off @
11,007, POH one piece & 16 jts of 4 1/2 DP & 4 DC's, ran WO mill
on 12 jts 8-1/8" WP to 10,370, CO to 11,007, WO DC's to
11,359, POH, ran DC's, jars & DP to 11,007, screwed into fish,
jarred fish up hole 65', cont to work fish up hole.

SANTA FE PACIFIC #10

11/14 (51) 11,650 drlg lm, 8-3/4" hole, NND, 9.8-58-8.0, 5% oil.
finish working fish loose, POH, rec all fish, ran mill
tooth bit, CO to bottom, drld 10', now POH w/ bit.