NO. OF COPIES	RECEIVED				
DISTRIBU					Form C-103 Supersedes Old
SANTA FE				COMMISSION	C-102 and C-103
FILE			MEXICO OIL CONSERVATION	COMMISSION	Effective 1-1-65
U.S.G.S.			i -		5a. Indicate Type of Lease
LAND OFFICE					
			•		5. State Oil & Gas Lease No.
OPERATOR]			E-1347
	CLINI			······································	
(DO NOT	USE THIS FORM FOR	PROPOSALS TO DRILL C	ND REPORTS ON WELLS or to deepen or plug back to a diff "(form C-101) for such proposals.	FERENT RESERVOIR.	
1.	USE "APPLIC	ATION FOR PERMIT	(FORM C-101) FOR SUCH PROPOSALS.	,) 	7. Unit Agreement Name
OIL GAS GAS VELL OTHER.					
2. Name of Operator					8. Farm or Lease Name
Anderson 011 and Gas Company, Inc.					State "35"
3. Address of Op		diding Midi	and Texas 79701		9. Well No.
2.5U MI		uilding, Midl	anu, iexas 75701	s	10 Field and Deel, on Wildow
• •	F	1830	West	1980	10. Field and Pool, or Wildcat
UN!" LETTER	· · · · ·	FEET F	FROM THE LINE AND	FEET FRO	
No	rth	35	11- S	33 - E	
тне.	LINE, SE	TION	TOWNSHIP RANGE		~ ())))))))))))))))))))))))))))))))))))
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	mmm	15 F1	levation (Show whether DF, RT, GR,	etc.)	12. County
			4233 GL		Lea
	mm		······		
	Chec	k Appropriate B	Box To Indicate Nature of N	Notice, Report or O	ther Data
	NOTICE OF	INTENTION TO):	SUBSEQUEN	NT REPORT OF:
				** ***	F 1
PERFORM REMEDI	IAL WORK	P	PLUG AND ABANDON REMEDIAL V	VORK	ALTERING CASING
TEMPORARILY AB	ANDON		COMMENCE	DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OF ALTER C	ASING	c	CHANGE PLANS CASING TES	T AND CEMENT JOB	
			OTHER		
OTHER			[]		
7 Describe Ero	posed or Completed	Operations (Clearly	state all pertinent details and give	pertinent dates includi	ng estimated date of starting any proposed
work) SEE R	RULE 1103.				
12 - 1072	Rig up Poo	1 Well Servin	ce unit. Ran correla	tion log, and p	erforated the Lwr. Pennsyl
	vanian For	mation from f	9781' to 9111' with 2	5 - 3/8" holes.	
12-11-72					9825" on 2-3/8" N-80 tubin
12-12-72	Acidized p	erforations 4	from 9781' to 9111' w	ith 4500 gallon	s 15% DS-30 Acid.
12-13-72	Well swabb	ed dry. Pul'	led tubing BP and RTTS	s tool.	
12-14-72					holes and from 8743 to 864
		3/8" holes.			
12-1 5-72			BP and RTTS tool and	ran in well to	9356' on 2-3/8" N-80 tubin
12-16-72			s from 9380' to 9111'		
12-10-72			tank. Well swabbed di		VIIS IJA DJ-JU ALIU.
12-18-72					
12 - 19-72					
.					ool, BP and 2-3/8" tubing.
12-20-72					on 2-3/8" N-80 tubing.
12-21-72			from 8743' to 8645' w		
12-22-72	Swabbed we	11 to test to	ank. Well swabbing a	nd flowing 1 0 b	bl. of fluid/hour est.
	25% oil.		-	~	-
12-23-72 to	-				
12-25-72		pumping equi	ipment.		(Over)
	by that the informat	ion about in town one			
In Inc. COV CET	y mat the intormat		I complete to the best of my knowled	lore and belief	
	//		d complete to the best of my knowled	dge and belief.	
	all At	И! I.			1
SIGNED	elland.	И! I.	d complete to the best of my knowled		DATE 4-30. 73
		Chu			DATE 4-30 73
		И! I.			DATE 4-30-73
Jel 1		Chu		er	DATE DATE

Continued from Side 1

- 12-26-72Retrieved BP @ 8877' and pulled BP, RTTS tool, and 2-3/8" N-80 tubing.12-27-72Ran 2-3/8" tubing in well with seating npl @ 9006' and mud anchor @ 9044'.12-28-72Waiting on sucker rods and down hole pump.12-29-72Ran 2" x 1-1/2" x 22' pump to 9006' with 262 3/4", and 96 7/8" sucker rods.12-30-72M-ove in 456 National Pumping unit with 120" stroke and Ajax engine.12-31-72Set up pumping unit and start well pumping.1-1-73 toI-4-731-5-73Ajax engine down, waiting for Ajax mechanic.1-5-73Repair engine, start well pumping
 - 1- 6-73 to

1-24-73 Pumping well to test tank. Well pumping 21 barrels of load oil plus 14 barrels of salt water per day.

- 1-25-73 All load recovered. Well pumping 5 BO + 35 BSW per day.
- 1-26-73 Shut well in prep to plug and abandon.