State of New Mexico Energy, ...nerals and Natural Resources Department

Form C-103 Revised 1-1-89

FEE

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

OIL CONSERVATION DIVISION

P.O. Box 2	2088
------------	------

Santa Fe, New Mexico 87504-2088

TEATT I	A TOT	NIO
WELL	API	NO.

30) – 02	5-2	<u>44</u>	<u>92</u>

5. Indicate Type of Lease STATE

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name
1. Type of Well:	EXCHANGE OIL & GAS
OIL WELL OTHER	8. Well No.
2. Name of Operator CARR WELL SERVICE, INC.	1
3. Address of Operator	9. Pool name or Wildcat
P.O. BOX 69090 ODESSA TX 79769-9090	VADA (PENN)
771 11 T	60 Fact From The FAST Line
Unit Letter P: 660 Feet From The SOUTH Line and 66	Tea riom ruo
Section 13 Township 9-S Range 33-E 10. Elevation (Show whether DF, RKB, RT, GR, etc.)	NMPM FA County
///////////////////////////////////////	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
//////////////////////////////////////	Penart or Other Data
Check Appropriate Box to Indicate Nature of Notice,	JBSEQUENT REPORT OF:
NOTICE OF INTENTION TO:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL	ING OPNS. PLUG AND ABANDONMENT 🔀
PULL OR ALTER CASING CASING TEST AND	CEMENT JOB
OTHER:	· · · · · · · · · · · · · · · · · · ·
OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, is work) SEE RULE 1103.	ncluding estimated date of starting any proposed
RIH SET CIBP @9575 CAP W/35 SX CMT 3-1-90 CUT 5-1/2 CSG @4000 PULL & LAY DOWN 3-2-90 RIH W/129 JTS TBG TO 4063 MIX & PUMP 50 SX CMT WOC & TA RIH W/WIRELINE PERF 8-5/8 CSG @1930 RIH W/59 JTS TBG TO CUT 8-5/8 CSG @738 PULL & LAY DOWN 3-6-90 RIH @/25 JTS TBG MIX & PUMP 50 SX CMT WOC & TAG @670 3 RIH W/15 FTS TO 472 MIX & PUMP 75 SX WOC & TAG @365 3 RIH W/1 JT TBG PUMP CMT TO SURF. 3-7-90 CUT OFF WELLHEAD, INSTALL DRY HOLE MARKER 3-7-90	1875 SQUEEZE 70 SA CM1 3-3-90
PULLED 752' OF 8-5/8 CSG PULLED 3885' OF 5-1/2 CSG	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	0 20 00
12. Mr. J. TIME PRESIDEN	NT DATE 9-30-92
SIONATURE PEN MONTCOMEDY	TELEPHONE NO. 915-36243
TYPE OR PRINT NAME BEN MONTGOMERY	
(This space for State Use)	OCT 1 3 '92
Jack Griffin me OIL &	GAS INSPECTOR JULY 18 92

APPROVED BY

CONDITIONS OF AFFROVAL, IF ANY: