NO. OF COPIES RECEIVED		•	Form C-103	
DISTRIBUTION			Supersedes (	
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION		C-102 and C-103 Effective 1-1-65	
FILE	1			-03
U.S.G.S.	1		5a. Indicate Typ	e of Lease
LAND OFFICE	†		State	Fee X
OPERATOR	4		5. State Oil & G	
OT ENATOR	J		J. Sidie Off & G	15 Ledge No.
			himming.	······
SUNDRY NOTICES AND REPORTS ON WELLS TO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.				
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)				
OIL V GAS			7. Unit Agreeme	at Name
WELL WELL	OTHER-			
2. Name of Operator			8. Farm or Leas	e liame
BTA OIL PRODUCERS			Brewer, 689-C Ltd.	
3. Address of Operator			9. Well No.	
104 South Pecos Midland, Texas 79701			2	
4. Location of Well			10. Field and Pool, or Wildcat	
UNIT LETTER "H" 1900 FEET FROM THE NORTH LINE AND 560 FEET FROM			Bagley, North (Penn.)	
UNIT LETTER FEET FROM THE LINE AND FEET FROM			VIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	
THE East LINE, SECTION 6 TOWNSHIP 12-S MANGE 33-E NMPM.				
THELINE, SECT	ON TOWNSHIP	AANGE JJ-L NMPM.		
mmmmmm	15. Elevation (Show whether I	OF RT CR etc.)	12. County	<del>4444444</del>
	4289' GR	,, on, e.e.,	1	
16.			Lea	<u> </u>
Check	Appropriate Box To Indicate Na	ature of Notice, Report or Otl	ner Data	
NOTICE OF I	NTENTION TO:	SUBSEQUENT	REPORT OF	:
				_
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTER	RING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.		AND ABANDONMENT Y
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB		ing harmoniment (M)
		OTHER		
OTHER				
17. Describe Proposed or Completed O	perations (Clearly state all pertinent detai	ils, and give pertinent dates, including	estimated date of	starting any proposed
work) SEE RULE 1703.	1			
<sup>2</sup> 3/10/84 TD 10,40	00'. Spotted 40 sx plug @	OFOO! Upable to Tax		
· Snotte	1 2nd 10 ex nlug @ 0500!	NOC 12 has Table 10 lay.	- 0 70001	
Spotted 2nd 40 sx plug @ 8500'. WOC 12 hrs. Tagged plug @ 7880'. Shot $5\frac{1}{2}$ " csg @ 5500'. LD 141 Jts. (5,515.06') of $5\frac{1}{2}$ " csg.				
. 50+ 40	2 CS9 6 5500 . LD 141 C	765. (0,015.06°) OT 5 ½"	csg.	
0+ 35C	sx @ 5550', 40 sx @ 5200'	, 50 SX @ 3/5/ , Pert 8	-5/8" csg 0	1750'
0 3420 0 + 75	w/60 sx. Shot 8-5/8" csg	) 6 313, 'rh 31 Ats (318	.16') of 8-	5/8" csg.
Set /5	sx @ 963'. 75 sx @ 450'.	10 sx @ Surface.		
Install	led Dry Hole Marker. P&A			
	·			
•				
7				
		·		
18. I hereby certify that the information	a shove is true and complete to the best of	my knowledge and belief.		
12.1.1/		<del>-</del>		
MIK March	DOD I NEW AND	udatan Alistit		
SIGNED / DV-11.1VWV / and	BOB K. NEWLAND TITLE Req	ulatory Administrator	DATE 3/1	5/84
Davit	2/4 O.	IL & GAS INSPECTOR	t JUI	2 6 1984

CONDITIONS OF APPROVAL, IF ANY