

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator <b>Texas Oil &amp; Gas Corp.</b> 3. Address of Operator <b>P. O. Box 591, Midland, Texas 79701</b> 4. Location of Well UNIT LETTER <b>E</b> , <b>1980</b> FEET FROM THE <b>north</b> LINE AND <b>660</b> FEET FROM THE <b>west</b> LINE, SECTION <b>11</b> TOWNSHIP <b>10-S</b> RANGE <b>32-E</b> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) <b>4287' GR</b>	7. Unit Agreement Name 8. Farm or Lease Name <b>State of New Mexico "A"</b> 9. Well No. <b>1</b> 10. Field and Pool, or Wildcat <b>Mescalero (Cisco)</b> 12. County <b>Lea</b>
---	--

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 7-22-74 Spudded well and drilled to 350'. Set 12 3/4" 42# H-40 csg at 350'. Cmtd with 400 sx Cl "C". Cmt circ. WOC 12'. Tstd csg to 800# with rig pump for 30" - OK
- 7-27-74 Set 8 5/8" 24# & 32#, J-55 csg at 3422'. Cmtd with 300 sx Cl "H". WOC 14'. Tstd csg to 1000# with rig pump for 30" - OK.
- 8-24-74 Set 5 1/2" 17# K-55 csg at TD 9100'. Cmtd with 450 sx. WOC 7 days. Tstd csg with Howco pump truck to 3000# for 30" - OK

Now attempting completion of well

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>Les Clements</i></u> <b>Les Clements</b>	TITLE <b>Staff Engineer</b>	DATE <b>11-22-74</b>
APPROVED BY <u>                    </u>	TITLE <u>                    </u>	DATE <u>                    </u>
CONDITIONS OF APPROVAL, IF ANY:		