

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-24855
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG 1736

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Hugh 689-C
2. Name of Operator BTA Oil Producers	8. Well No. 1
3. Address of Operator 104 S. Pecos; Midland, Texas 79701	9. Pool name or Wildcat N. Bagley, Permo Penn
4. Well Location Unit Letter I : 2080 Feet From The South Line and 560 Feet From The East Line Section 6 Township 12-S Range 33-E NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4294 GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Proposed Plugging Procedure

Set CIBP @ 8500' w/35' cmt on top
Cut & pull 5-1/2" csg. Top of cmt @ 7425'
Spot 50 sx plug across 5-1/2" csg stub
Spot 50 sx plug @ 5500' (Glorietta)
Spot 50 sx plug across 8-5/8" shoe @ 3730'
Cut & pull 8-5/8" csg. Top of cmt @ 2250'
Spot 75 sx plug across 8-5/8" csg stub
Spot 75 sx plug across 12-3/4" csg shoe @ 380'
10 sx plug @ surface and install dry hole marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R. D. Boyce TITLE Production Supervisor DATE 09/17/91
TYPE OR PRINT NAME R. D. Boyce TELEPHONE NO. 682-3753

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

SEP 19 1991

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED.