

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Kerr McGee Corporation

3. Address and Telephone No.

P.O. Box 11050 Midland, Texas (915) 688-7000

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FEL & 2180' FNL of Section 23, T-9-S, R-37-E

unit 2

5. Lease Designation and Serial No.

LC - 065151

6. Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Bilbrey 51 #3

9. API Well No.

30-025-25075

10. Field and Pool, or Exploratory Area

Sawyer (San Andres) Assoc

11. County or Parish, State

Lea

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other REMEDIAL WORK
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7-10-90 TOH w/ pmp & rods. PU tbg. TIH & tagged bottom. PBTD 5040.89', SN @ 4988.56' bottom perf @ 5032'. NU BOP. SDON.

7-11-90 RIH w/ junk basket & gauge ring. Ran GR-CCL from PBTD 5044-4500', perf from 4966-74 w/ 2 JSPF (17 holes) & 4979-89' w/ 2 JSPF (21 holes) Total of 38 holes. TIH w/ pkr & RBP. Set RBP @ 5044'. POH & set pkr @ 5000'.

7-12-90 Acidized old perfs 5012-34' (21 holes) w/500 gal 15% DS acid & 1500 gal 15% NEFE. Dropped ball sealers in (4) four stages. Released pkr. TIH catch RBP. POOH & set RBP @ 5000' set pkr @ 4902'. Acid frac new perfs 4966-89' w/500 gal 15% DAD, & 4500 gal 20% NEFE & 4500 gal YF - 120 psg. Swab well. TIH w/ SN & 2 3/8" tbg. SN @ 5035'. Returned to prod.

8-1-90 24 hour test 6.9 BO & 21 BW. Prior rate 2.1 BOPD & 0.1 BW.

FILED FOR RECORD

SEP 18 1990

14. I hereby certify that the foregoing is true and correct

Signature

Title

CARLSBAD, NEW MEXICO

Date

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any: