

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG 0622	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Julian Ard		8. Farm or Lease Name Harton-State
3. Address of Operator 303 Main Street, Suite 302, Ft. Worth, TX 76102		9. Well No. 1
4. Location of Well UNIT LETTER <u>0</u> , <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>32</u> TOWNSHIP <u>9S</u> RANGE <u>37E</u> NMPM.		10. Field and Pool, or Wildcat Sawyer West, San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 3799 GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-1-87

4900' Set CIBP w/35' cement on top.
FILL CASING WITH SALT GEL MUD TO A BRINE W/25% GEL/100% GEL
2270' Perforate 4 holes, squeeze 25 sx cement outside casing. Leave retainer w/35' in casing.
405' 100' plug 25 sx across surface, shove 50' in, 50' outside.
10' Sx plug at surface. Dry hole marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE PERFORMING OF PLUG AND OPERATIONS FOR THE C-103 TO BE APPROVED

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Paula Rozeiman TITLE Production Clerk DATE February 6, 1987

Orig. Signed by Paul Kautz TITLE Geologist DATE FEB 9 1987
APPROVED BY Geologist
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
FEB 9 1987
OCD
HOBBS OFFICE