

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
LG 0623

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CLEAN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - FORM C-1011 FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Julian Ard

3. Address of Operator
P. O. Box 2361, Midland, Texas 79702

4. Location of Well
UNIT LETTER P 660 South 660
FEET FROM THE LINE AND FEET FROM
THE East 32 9S 38E
LINE, SECTION TOWNSHIP RANGE NMPM.

7. Unit Agreement Name

8. Form or Lease Name
State 32

9. Well No.
1 1

10. Field and Pool, or Wildcat
Sawyer

15. Elevation (Show whether DF, RT, GR, etc.)
3917 GR

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We plan to start plugging operations on December 26, 1977.
Anticipated casing recovery will be approximately 3700' of 4-1/2" casing.
Plugs to be set as follows with heavy mud between plugs:
Cast Iron Bridge Plug to be set at 4900, with 35 feet of cement on top.
100 ft. cement plug in and out of 4-1/2" stub.
100 ft. cement plug at base of salt, if not behind pipe.
100 ft. cement plug at top of salt, if not behind pipe.
If behind pipe, 100 ft. plug inside 4-1/2" at approximate top of salt.
100 sx. plug at shoe on 8-5/8".
10 sx. plug at surface with well marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Betty Thompson TITLE Agent DATE December 14, 1977

APPROVED BY Orig. Signed by Jerry Sexton TITLE Dist 1, Supv. DATE DEC 16 1977

CONDITIONS OF APPROVAL, IF ANY: