Form 9-331 (May 1963)		NITED STATES		SUBMIT IN TRIPLE ATE (Other Instruction re		Form approved. Budget Bureau No. 42–R1424.		
	DEPARTM	EI OF THE INTERIO	NTERIOR	R verse side)		5. LEASE DESIGNATION AND BERIAL NO.		
	GI	GEOLOGICAL SURVEY				NM-066884-A		
		LES AND REPC s to drill or to deepen ION FOR PERMIT-" f			· ·	6. IF INDIAN, ALLOTTEE	OR TRIBE NAME	
1. OIL X GAS WELL OTHER						7. UNIT AGREEMENT NAME		
2. NAME OF OPERATOR						8. FARM OR LEASE NAME		
Flag-Redfern Oil Company						Brown "84"		
3. ADDRESS OF OPERATOR						9. WELL NO.		
P. O. Box 23, Midland, Texas 79701						2		
 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.[•] See also space 17 below.) At surface 						10. FIELD AND POOL, OR WILDCAT Sawyer (San Andres)		
860' FWL & 660' FSL						11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA		
					1	Sec. 13, T-9	-S, R-37-E	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.)				12. COUNTY OR PARISH	13. STATE	
		395	58' GR			Lea.	New Mexico	
16.	Check App	propriate Box To Ind	licate Natur	e of Notice, Report, o	r Ot	her Data		
NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:				
• TEST WATER SHC	T-OFF PU	LL OR ALTER CASING		WATER SHUT-OFF		REPAIRING W	ELL	
FRACTURE TREAT	и	CLTIPLE COMPLETE		FRACTURE TREATMENT		ALTERING CA	SING	
SHOOT OR ACIDIZE	AE	ANDON*		SHOOTING OR ACIDIZING		ABANDONMEN		
REPAIR WELL	REPAIR WELL CHANGE PLANS			(Other) Set production csg X				
(Other)				(NOTE: Report res Completion or Reco	uits of mplet	f multiple completion of ion Report and Log for:	on Well m.)	
17. DESCRIBE PROPOSED	OR COMPLETED OPER.	TIONS (Clearly state all	pertinent det	ails, and give pertinent da	tes, ir	cluding estimated date	of starting any	

2

t

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drilled 7-7/8" hole to 5025'. Ran Sidewall Neutron Porosity log by Schlumberger. Set $4\frac{1}{2}$ ", 10.5#/ft, K-55, ST&C csg at 5025' w/stage collar at 2391'. Pumped 500 gals mud flush. Cemented w/250 sx Class "C" Pozmix, 2% gel, 3/4% CFR-2, 8 lbs salt. PD at 4:45 P.M., 6-28-76. Released rig. WOC. Picked up shifting tool & tbg & WIH to 2391'. Opened stage cementing collar. Est/circ & cmt'd w/850 sx Halliburton Light cmt w/0.4% CFR-2 & 8 lbs salt. Circ out 400 sx. Closed stage collar & reversed out cmt. WIH w/tbg to PBTD, circ hole & spotted 250 gals 15% acid. TOH. Perforated 4914-5003' & treated.

18. I hereby certify that the foregoing is true and correct								
SIGNED Diplos H. Manuel	TITLE _	Production Manager	DATE 7-13-76					
(This space for Federal or State office use)			ACCEPTED FOR RECORD					
APPROVED BY	TITLE _		DATE					
CONDITIONS OF APPROVAL, IF ANY:			JUL 1 9 1976					
			J. S. GEOLOGICAL SURVEY					
*S	ee Instruct	ions on Reverse Side	HOBBS, NEW MEXICO					
			· · · · · · · · · · · · · · · · · · ·					