

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator FEATHERSTONE DEVELOPMENT CORPORATION		8. Farm or Lease Name SANTA FE
3. Address of Operator 1717 WEST SECOND, ROSWELL, NM 88201		9. Well No. #1
4. Location of Well UNIT LETTER <u>F</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>2310</u> FEET FROM THE <u>West</u> LINE, SECTION <u>21</u> TOWNSHIP <u>10 S.</u> RANGE <u>37 E.</u> NMPM.		10. Field and Pool, or Wildcat North Echol-Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 3947' GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
-------------------------	-----------------------

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/17/77 10:30 A.M. Spud Well.
4/1/77 12,042' TD Drillers, 12,005' Loggers TD
Intend to plug & abandon as follows: - Log Measurements -
100' Cement Plug 35 Sacks from 12,005' (TD) to 11,905'
100' " " " " " 11,300' to 11,200' - Top Atoka
100' " " " " " 9,950' to 9,850' - Top Penn.
100' " " " " " 9,150' to 9,050' - Top Wolfcamp
100' " " " " " 7,800' to 7,700' - Top ABO
100' " " " " " 5,700' to 5,600' - Top Glorietta
270' " " 100 " " 5,290' to 5,020' - San Andres Water Zone
(Bottom 8 5/8" at 4,250' covered by the following plug)
100' Cement Plug 35 Sacks from 4,300' to 4,200' - Top San Andres
100' " " " " " 2,400' to 2,300' - Top Salt
Will set 10 sacks cement plug at top with 4 1/2" Marker Pipe 4' above surface.
Will breakout pits and level location and pit area.

Expires 10-13-77

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles W. Hicks TITLE Vice President DATE 4/8/77

APPROVED BY Orig. Signed by Jerry Sexton TITLE Dist 1, Supv. DATE APR 13 1977

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 12 1977

OIL CONSERVATION COMM.
WASH. D.C.