

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator John L. Cox		8. Farm or Lease Name Proctor
3. Address of Operator P. O. Box 2217, Midland, Texas 79702		9. Well No. 1
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>7</u> TOWNSHIP <u>11-S</u> RANGE <u>32-E</u> N.M.P.M.		10. Field and Pool, or Wildcat Lera-Morrow
15. Elevation (Show whether DF, RT, GR, etc.) 4472.6' GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-23-91: Moved in and Rigged up to P&A.

9-24-91: Set CIBP @10,868 w/35' cement on top.

9-25-91: Spot 25 sx cement plug @8340' (Top Wolfcamp 8338')
Spot 25 sx cement plug @7245' (Top Abo @7240')

9-26-91: Cut and recovered 4727' 5-1/2" casing.
Spot 40 sx cement plug @4767' (Tagged top of plug @4635').
Spot 45 sx cement plug @4336'.

9-27-91: Tagged top of plug @4273', spot additional 20 sx cement.
Spot 35 sx cement plug @2150' (Base of Salt @2144').
Spot 35 sx cement plug @417'.
Spot 10 sx cement plug from 30' to surface.
Well filled with mud-laden fluid.
Set Well Marker.
Plugging completed 9-27-91.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Walter K. Kutt</u>	TITLE <u>Prod. Mgr.</u>	DATE <u>10/22/91</u>
APPROVED BY <u>Wm. M. Liel</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>OCT 29 1991</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

OCT 23 1991

0-23
HOBBS OFFICE