NO. OF COPIES PECCIVED	Form C-103
DISTRIBUTION	Supersedes Old C-102 and C-103
SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE	
U.S.G.\$.	5a, Indicate Type of Lease
LAND OFFICE	State XX Fee
OPERATOR	5. State Oil & Gas Lease No. V - 16
	mmmm
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR PROPURALS TO DRILL ON TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.	
USE "APPLICATION FOR PLANIT -" (FORM C-101) FOR SUC- PROPOSALS.	7. Unit Agreement Name
OIL CAS OTHER.	
2. Name of Operator	E. Farm or Lease liane
Southern Union Exploration Company of Texas	Susco Bough "C" Unit
i. Address of Operator	9. Well No.
1217 Main Street, Dallas, Texas 75202	# 1
Location of Well	10. Field and Posi, or Wilcom
UNIT LETTER J . 1980 FEET FROM THE FAST LINE AND 33 F FEET FROM	Vada Inbe Penn- Bench "(
THE South LINE, SECTION 35 TOWNSHIP 10 S RANGE 33 E NAPH.	
15, Elevation (Show whether DF, RT, GR, etc.)	12. County
4196.5' GR	LEA ())))))
Check Appropriate Box To Indicate Nature of Notice, Report or Other	er Data
NOTICE OF INTENTION TO: SUBSEQUENT	REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND CEMENT JOE XXXX	. [7]
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including e work) SEE RULE 1703.	stimated date of starting any proposed
Den 00511 of 5 1/011 1711/61 N 00 THIS	•
Ran 9951' of 5 1/2", 17#/ft., N-80, LT&C casing on 7-16-81. There were 2	
at 8990' and the other at 6850'. Cemented on 7-16-81 w/2330 sacks Class 1314# of Halad 26 as follows:	H w/1864 # salt +
1514# Of hard 20 as follows: 1st stage: pump 10 BW + 25 Bbls cement, drop 1st DV plug and displace wi	th 220 Phla of mid
Circ. for 6 hrs.	th 230 Bbis of mud.
2nd stage: Pump 10BW + 117 Bbls cement, drop send plug and displace with	210 Bbls of mid
Circ. for 6 hrs.	210 Bolb of Mad.
3rd stage: Pump 10BW and 319 Bbls cement, drop closing plug and displace	with 119 Bbls of mud.
Bump plug with 2100 psi.	
D 111	
Drill out cement to 9915' and test casing to 1500 psi for 15 minutes on 7	-23-81.
	•
	27
	4 7 4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	47
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
D. J. M. W. A. A.	DATE September 28 109
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  TITLE Drlg. & Prod. Engineer	DATE September 28, 198
Pot M. Harrellips TITLE Drlg. & Prod. Engineer	DATE September 28, 198
D. J. M. W. A. A.	September 28, 198