DISTRIBUTION NEW MEXICO OIL CONSERVATION COMMISSION CITY of Loss SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS TO SUNDRY NOTICES AND REPORTS ON THE PROPERTY OF THE PROPERTY ON TH	NI. OF COPIES RECEIVED				Form C-103 Supersedes O	lď	
So. Indicate 7 Free So.	DISTRIBUTION				C-102 and C-1	C-102 and C-103	
U.S. of S. Some OU S. Cons. Leave No.	SANTA FE	NEW	MEXICO OIL CONSE	RVATION COMMISSION	Effective 1-1-	65	
SUNDRY NOTICES AND REPORTS ON WELLS BOUNDRY NOTICES AND REPORTS ON WELLS BOUNDRY NOTICES AND REPORTS ON WELLS BOUNDRY NOTICES AND REPORTS ON WELLS BY A COMMENT OF THE PROPERTY OF THE PRO	FILE				Sa. Indicate Type	of Lease	
Symbols Notices and Reports on Wells Continue					State X	Fee 🗌	
SUBDRY NOTICES AND REPORTS ON WELLS OF A STATE OF THE CONTROL OF						is Lease No.	
Check Appropriate Box To Indicate Nature of Notice, Report of Other Data Notice of Complete Notice of Show whether DF, RT, GR, res.	OPERATOR	<u> </u>			· L 6834		
Remote Consider State Brazos Petroleum Company 1. Remote Consider State Brazos Petroleum Bldg Midland, Texas 79701 1. Common Well Lections Well Leaf Crossroads (Com Annual John Lections Company) 10. First and Remote Dr. RT. CR. etc.) 12. Commy 13. Elevation (Show whether Dr. RT. CR. etc.) 13. Commy 14. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: Lea NOTICE OF INTENTION TO: Lea Leaf Company Leaf Place Company Consists Annual Company Appropriate Company Properties and Lection Company Properties and Lec	(DO NOT USE THIS FO	SUNDRY NOTICES AN	D REPORTS ON	WELLS			
Brazos Petroleum Company Red	1.		Treatment of the same		7. Unit Agreemen	it Name	
Brazos Petroleum Company Address of Common Company Alsoes of Common Company 1. Localized Science State 1. Localized Science Science Science State 1. Localized Science Science Science State 1. Localized Science Sc		DTHER-			8. Farm or Lease	Name	
1. Address of Greenest 708 Petroleum Bldg Midland, Texas 79701 2. Localized of Well 2. Localized of Completed Operations (Show whether Df., RT, CR, etc.) 3979.1 GL Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: 2. Subsection West 2. Localized West 2. Localize							
10. Field on Pool, or Viscotion 10. Field and Pool, or Viscotion 10. Secretary 1 10. Secretary 1 10. Secretary 1							
East Crossroads (San Anterior J 1980	4. Location of Well				1	•	
10-8 ************************************	J	1980 FEET FF	OM THE South	LINE AND 1980 FEET	Fast Crossr	oads (San And	
15. Elevention (Show whether DF, RT, GR, etc.) 3979.1 GL Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PLUE AND ARABODN PULL OR ALTER CASINE CHANGE PLANS C					(///////		
15. Elevention (Show whether DF, RT, GR, etc.) 3979.1 GL Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PLUC AND ASANDON RECURSIAN MORE TEMPORATILY ASANDON PULL OR ALTER CASINE OTHER 7-8-81 W.I.H. with 153 jts. (4891') 2 3/8" 4.7# J55"Tbg. O.E., Circulated hole with 2% KCL Water & spotted 100 gals, acid, POH with tbg, WIH with perforating gun lacked 5' getting to TD to perforate, WIH with tbg with tapped bull plug, jetted thru tbg with 2% KCL Water could not make any hole, POH with tbg. SDON will GIH with 4 3/4" bit & bit sub on tbg this A.M. & clean out, rotating tbg. 10.1 hereby cently that the information above is true and complete to the best of my knowledge and helief. 10.2 Signed By Jerry Sasten 10.3 Sasten 10.4 Sasten 10.5 Signed By Jerry Sasten 10.6 Sasten 10.7 Signed By Jerry Sasten 10.7 Signed By Jerry Sasten	THE East	INE. SECTION 7	TOWNSHIP 10-S	RANGE 37-E	NMPM.		
Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: PEUC AND ARABDON PULL ON ALTER CASING OTHER 77-8-81 W.I.H. with 153 jts. (4891') 2 3/8" 4.7# J55 Tbg. O.E., Circulated hole with 2% KCL Water & spotted 100 gals, acid, POH with tbg, WIH with perforating gun lacked 5' getting to TD to perforate, WIH with tbg with tapped bull plug, jetted thru tbg with 2% KCL Water could not make any hole, POH with tbg. SDON will off with 4 3/4" bit & bit sub on tbg this A.M. & clean out, rotating tbg. 10.1 hereby certify that the information above is vive and complete to the best of my knowledge and belief. Orig. Signed By Berry Sasters. 110.2 Signed By Berry Sasters. 110.3 Production Clerk PLUC AND ARABDON ACTUALIZED ATTUAL CASING ACTUAL CASING CASING TEST AND CEMENT JOB. ACTUAL CASING TEST AND CEMENT JOB			•			7////////	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PLATORM REMEDIAL WORK PLUE AND ARABDON SUBSEQUENT REPORT OF: ALTERISE CASING OUNTRIES SUBSEQUENT REPORT OF: OUNTRIES SUBSEQUENT REPORT OF: ALTERISE CASING OUNTRIES SUBSEQUENT REPORT OF: ALTERI				77, K1, OK, CICI,			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: SUB	16.	Check Appropriate Be		ature of Notice, Report of	or Other Data		
PLUE AND ABANDON	NOTIO			SUBSEQ	UENT REPORT OF:		
TEMPORABLY ARANGON PULL OR ALTER CASINE OTHER TWO Describe Proposed or Completed Operations (Clearly store all pertinent details, and give pertinent dates, including estimated date of starting ony proposed work) see mult 103. 7-8-81 W.I.H. with 153 jts. (4891') 2 3/8" 4.7# J55 Tbg. O.E., Circulated hole with 2% KCL Water & spotted 100 gals, acid, POH with tbg, WIH with perforating gun lacked 5' getting to TD to perforate, WIH with tbg with tapped bull plug, jetted thru tbg with 2% KCL Water could not make any hole, POH with tbg. SDON will GIH with 4 3/4" bit & bit sub on tbg this A.M. & clean out, rotating tbg. with tbg tongs.				_	_		
TV. Describe Proposed of Completed Operations (Clearly store all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) see nutt 103. 7-8-81 W.I.H. with 153 jts. (4891') 2 3/8" 4.7# J55"Tbg. O.E., Circulated hole with 2% KCL Water & spotted 100 gals, acid, POH with tbg, WIH with perforating gun lacked 5' getting to TD to perforate, WIH with tbg with tapped bull plug, jetted thru tbg with 2% KCL Water could not make any hole, POH with tbg. SDON will GIH with 4 3/4" bit & bit sub on tbg this A.M. & clean out, rotating tbg. With tbg tongs.	PERFORM REMEDIAL WORK	Pf	LUG AND ABANDON	REMEDIAL WORK	ALTER	ING CASING	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1105. 7-8-81 W.I.H. with 153 jts. (4891') 2 3/8" 4.7# J55 Tbg. O.E., Circulated hole with 2% KCL Water & spotted 100 gals, acid, POH with tbg, WIH with perforating gun lacked 5' getting to TD to perforate, WIH with tbg with tapped bull plug, jetted thru tbg with 2% KCL Water could not make any hole, POH with tbg. SDON will GIH with 4 3/4" bit & bit sub on tbg this A.M. & clean out, rotating tbg. with tbg tongs. 11. Thereby certify that the information whose is true and complete to the best of my knowledge and belief. 12. Thereby certify that the information whose is true and complete to the best of my knowledge and belief. 13. Thereby certify that the information whose is true and complete to the best of my knowledge and belief. 14. Thereby certify that the information whose is true and complete to the best of my knowledge and belief. 15. Thereby certify that the information whose is true and complete to the best of my knowledge and belief. 16. Thereby certify that the information whose is true and complete to the best of my knowledge and belief. 17. Thereby certify that the information whose is true and complete to the best of my knowledge and belief.	TEMPORARILY ABANDON]		COMMENCE DRILLING OPNS.	PLU6 /	LED ABANDONMENT	
17. Describe Froposed or Completed Operations (Clearly store all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE NULE 1103. 7-8-81 W.I.H. with 153 jts. (4891') 2 3/8" 4.7# J55 Tbg. O.E., Circulated hole with 2% KCL Water & spotted 100 gals, acid, POH with tbg, WIH with perforating gun lacked 5' getting to TD to perforate, WIH with tbg with tapped bull plug, jetted thru tbg with 2% KCL Water could not make any hole, POH with tbg. SDON will GIH with 4 3/4" bit & bit sub on tbg this A.M. & clean out, rotating tbg. with tbg tongs. 18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief. 18.2 hereby certify that the information above is true and complete to the best of my knowledge and belief. 18.3 hereby certify that the information above is true and complete to the best of my knowledge and belief. 18.4 hereby certify that the information above is true and complete to the best of my knowledge and belief. 18.4 hereby certify that the information above is true and complete to the best of my knowledge and belief. 18.5 hereby certify that the information above is true and complete to the best of my knowledge and belief. 18.6 Thereby certify that the information above is true and complete to the best of my knowledge and belief.	PULL OR ALTER CASING] "	ANGE PLANS		_		
17. Describe Frenoued or Completed Operations (Clearly store all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE WILE 1703. 7-8-81 W.I.H. with 153 jts. (4891') 2 3/8" 4.7# J55 Tbg. O.E., Circulated hole with 2% KCL Water & spotted 100 gals, acid, POH with tbg, WIH with perforating gun lacked 5' getting to TD to perforate, WIH with tbg with tapped bull plug, jetted thru tbg with 2% KCL Water could not make any hole, POH with tbg. SDON will GIH with 4 3/4" bit & bit sub on tbg this A.M. & clean out, rotating tbg. with tbg tongs. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.				OTHER			
7-8-81 W.I.H. with 153 jts. (4891') 2 3/8" 4.7# J55 Tbg. O.E., Circulated hole with 2% KCL Water & spotted 100 gals, acid, POH with tbg, WIH with perforating gun lacked 5' getting to TD to perforate, WIH with tbg with tapped bull plug, jetted thru tbg with 2% KCL Water could not make any hole, POH with tbg. SDON will GIH with 4 3/4" bit & bit sub on tbg this A.M. & clean out, rotating tbg. with tbg tongs. 11. I hereby certify that the information above to true and complete to the best of my knowledge and belief. 11. I hereby certify that the information above to true and complete to the best of my knowledge and belief. 11. I hereby certify that the information above to true and complete to the best of my knowledge and belief. 11. I hereby certify that the information above to true and complete to the best of my knowledge and belief. 11. I hereby certify that the information above to true and complete to the best of my knowledge and belief. 11. I hereby certify that the information above to true and complete to the best of my knowledge and belief. 11. I hereby certify that the information above to true and complete to the best of my knowledge and belief. 11. I hereby certify that the information above to true and complete to the best of my knowledge and belief. 11. I hereby certify that the information above to true and complete to the best of my knowledge and belief.							
7-8-81 W.I.H. with 153 jts. (4891') 2 3/8" 4.7# J55 Tbg. O.E., Circulated hole with 2% KCL Water & spotted 100 gals, acid, POH with tbg, WIH with perforating gun lacked 5' getting to TD to perforate, WIH with tbg with tapped bull plug, jetted thru tbg with 2% KCL Water could not make any hole, POH with tbg. SDON will GIH with 4 3/4" bit & bit sub on tbg this A.M. & clean out, rotating tbg. with tbg tongs. 11. I hereby certify that the information above to true and complete to the best of my knowledge and belief. 11. I hereby certify that the information above to true and complete to the best of my knowledge and belief. 11. I hereby certify that the information above to true and complete to the best of my knowledge and belief. 11. I hereby certify that the information above to true and complete to the best of my knowledge and belief. 11. I hereby certify that the information above to true and complete to the best of my knowledge and belief. 11. I hereby certify that the information above to true and complete to the best of my knowledge and belief. 11. I hereby certify that the information above to true and complete to the best of my knowledge and belief. 11. I hereby certify that the information above to true and complete to the best of my knowledge and belief. 11. I hereby certify that the information above to true and complete to the best of my knowledge and belief.	17. Describe Proposed or Co	mpleted Operations (Clearly	state all pertinent deta	ils, and give pertinent dates, inc	luding estimated date of	starting any proposed	
2% KCL Water & spotted 100 gals, acid, POH with tbg, WIH with perforating gun lacked 5' getting to TD to perforate, WIH with tbg with tapped bull plug, jetted thru tbg with 2% KCL Water could not make any hole, POH with tbg. SDON will GIH with 4 3/4" bit & bit sub on tbg this A.M. & clean out, rotating tbg. with tbg tongs. III. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Orth. Signed By Jerry Session.	work) SEE RULE 1103.						
Orig. Signed by Jerry Sexton Appearoned by Dist & Supple	2% KCL gun lac jetted will GI	Water & spotted 10 ked 5' getting to thru tbg with 2% K H with 4 3/4" bit	O gals, acid, TD to perforat CCL Water could	POH with tbg, WIH wite, WIH with tbg with not make any hole,	ith perforating h tapped bull pl POH with tbg. S	lug, SDON	
Orig. Signed by Jerry Sexton Appearoned by Dist & Supple	19 11 12 20 20 20 20 20	information above is true and	complete to the best of	f my knowledge and belief.			
Orig. Signed By Jerry Sexion APPROVED BY Disk is Supple.	ir. I nereby certify that the	(-		· -			
Orig. Signed by Jerry Sexion Approved by Disk is Supple.	SIGNED ANALE	the Can		oduction Clerk	DATE 7-	8-81	
Jerry Sexion.	Orie. Signe	ed By				. 500gs	
APPADVED BY DION L BUILT					DATE	·	