

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
K-6857

SUNDARY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR NOTICES TO WELL OR TO OPERATOR OR TO A DIFFERENT RESERVOIR.
USE THIS FORM FOR REPORTS ON WELLS ONLY.)

1. Kind of Well	2. Kind of Operator
OIL ☒ GAS ☐ OTHER ☐	V-F Petroleum Inc.
3. Address of Operator	4. Location of Well
One Marienfeld Place, Suite 580; Midland, Texas 79701	UNIT LETTER <u>P</u> <u>330</u> FEET FROM THE <u>South</u> LINE AND <u>330</u> FEET FROM THE <u>East</u> LINE, SECTION <u>32</u> TOWNSHIP <u>9S</u> RANGE <u>37E</u> NMPM.

7. Unit Agreement Name
8. Form of Lease Name
State 32
9. Well No.
2Y
10. Field and Pool, or Wildcat
West Sawyer, San Andres
12. County
Lea

11. Elevation (Show whether DF, RT, CR, etc.)
3972.3'

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
FULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☒	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1900.

9/20/83 - MI Butch's Rat Hole Service. Spud well at 12 noon 9/19/83-TD 35'. Wait on cable tools.
10/9 thru 10/22/83 - MI cable tools. Drill 17 1/2" hole to 230'. MO cable tools.
11/9/83 - MIRT. Drill 17 1/2" hole to 436'. Run 441' 12 3/4" csg. Cmt w/500 sx C1 "C" cmt. Did not circ. Run 1" in annulus. Cmt to surf w/300 sx - circ 25 sx to surf. Test csg to 800psi for 15 min. OK.
11/10 thru 11/13/83 - Drill 11" hole to 2270'. Run 2286' 8 5/8" csg. Cmt w/800 sc. Circ 40 sx to surf. Test csg to 1500psi for 30 min. OK.
11/14 thru 11/19/83 - Drill 7 7/8" hole to 5048'. Run 5049' 4 1/2" csg. Cmt w/1000 sx. Plug down at 4 AM 11/19/83. Rig released. Wait on completion unit.
11/29/83 - Perforate at 4963', 70', 71', 72', 73', 81', 83', 85', 91', 93', 94', 95' (12 holes).
11/30/83 - Acidize w/10,000 gal 20% HCl. Swab back load, run rods & pump, and POP.
12/13/83 - Pump 19 BO + 85 BW in 24 hrs. Well is completed.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>C. Engle</u>	TITLE <u>Operations Manager</u>	DATE <u>1/10/84</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT 1 SUPERVISOR	TITLE _____	DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JAN 12 1984