

through bad spot in 7" csg, ok. Tagged TOF @ 978', mulled over 3-1/2" tbg fish to 1005'. Stopped making hole. POOH. LD 1 jt WP – piece of tbg, jammed up WP and grapple. TIH w/ shoe, 1 jt WP, DC's & tbg. Milled over fish to 1023'. Stopped making hole. POOH – recovered 17' piece of tbg. Possibly piece of 3-1/2" tbg fell out of WP when fishing tools reached surface. 25' of 3-1/2" tbg recovered today. SION.
DC: \$5275 CC: \$106,550

- 12-30** SICP vac, PU 5-3/4" shoe w/grapple, WP, DC's & TIH on 2-7/8" tbg. Tag up @ 1020', worked dwn to 1023'. POOH, recovered 13' piece tbg. TIH w/shoe, tag up @ 1023', mill dwn to 1058', btm out. POOH, recovered 2 jts – 60' – collar together between jts. RIH w/shoe, worked mill shoe dwn to 1120', POOH, recovered 2 jts tbg – 61' – btm jt looked better. Total recovered for day – 134'. SI till Tuesday 1-2-2001.
DC: \$5,045 CC: \$111,595
- 01-03** ICP vac, PU 5-3/4" shoe w/grapple, WP, DC's & TIH on 2-7/8" tbg. Work mill to 1183', POOH, recovered 2 jts tbg 61'. TIH w/shoe, work dwn to 1242', POOH, recovered 2 jts – 60'. TIH w/shoe on 2-7/8" tbg, work dwn to 1330', pulled 40 pts over & came free – POOH, recovered 17 jts tbg. Jts covered w/scale & iron, but fewer holes. Top of fish @ 1750'. Total recovered for day 21 jts-630'. SION
DC: \$5,275 CC: \$116,870
- 01-04** SICP vac, PU 6-1/8" bit w/2 DC's & TIH on 2-7/8" tbg. Did not feel tight spot @ 415'. Circ dwn to 1783' & clean scale & iron off csg wall. POOH, TIH w/5-3/4" shoe, WP, DC's & 2-7/8" tbg – wash dwn to 1847' – pulled 55 pts over – came free – cannot determine if recovered fish. POOH, recovered 108' tbg – 3 jts & 18' piece. Total recovered for day – 108'. Tbg recovered had less scale on outside, but inside packed w/scale. Could not have got WL thru these jts. SION
DC: \$5,500 CC: \$122,370
- 01-05** SICP vac, PU 5-3/4" shoe, WP, DC's & TIH on 2-7/8" tbg – wash dwn to 1938' – latch collar – pulled 60 pts – tbg came up 10' then stopped. Worked tbg up & dwn – pulled up to 80 pts over – came free. POOH, grapple broke – did not recover fish. PU 5-3/4" shoe w/o grapple, 1 jt WP & TIH on 2-7/8" tbg – got over top of fish. RU sand line w/sinker bar & TIH. Tag up on top of fish @ 1890' – would not go thru. Top of fish could be folded in or full of scale. POOH w/SB, RD sand line. POOH w/shoe, PU 5-3/4" cut-rite mill, 4 jts WP, 2 DC's & TIH on 2-7/8" tbg – tag up @ 1938' – milled for 2 hrs - made 3" – very little returns of metal & scale. POOH above bad spot @ 415' & SION. Will run jars & pull fish this AM.
DC: \$6,050 CC: \$128,420
- 01-06** SICP vac, POOH w/tbg, DC's, WP & shoe. Btm & outside of shoe still new looking – had worn spot inside. PU 5-3/4" shoe w/3-1/2" grapple (will go after body-easier to get off) 6' extension, bumper sub, jars, DC's & TIH on 2-7/8" tbg. Latched on tbg body @ 1896' – pulled gradually up to 70 pts & came free. POOH, recovered 12' piece tbg – broke in middle of collar. TIH w/shoe w/4-3/8" grapple to catch collar. Latch collar @ 1903'. RU sdline – TIH w/1-1/4" SB – tag up @ ± 1925' – attempt to jar thru – would not go. POOH w/SB & RD sdline. Pull gradually to 40 pts & set off jars – pull to 75 pts & came free. POOH – did not recover fish. PU shoe w/4-1/4" grapple & TIH. Tag collar @ 1903' – rotate shoe on collar – would not latch – appears collar broke. POOH w/shoe. Will go after upset, PU shoe w/3-3/4" grapple & TIH to 350'. SION.
DC: \$7,205 CC: \$135,625
- 01-07** SICP vac. Continue TIH w/5-3/4" shoe & grapple for upset on tbg. Tag up 1' deeper @ 1904' – work grapple dwn 2' – would pull off @ 3 pts. May be pushing tbg dwn. POOH did not recover fish. Appears collar still on. May have been getting friction bite w/guide. PU 5-7/8" shoe w/4-