

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K-3920	

SUNDRY NOTICES AND REPORTS ON WELLS <small>DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Wagner and Brown		8. Farm or Lease Name Cleveland
3. Address of Operator P. O. Box 1714, Midland, Texas 79702		9. Well No. 2
4. Location of Well UNIT LETTER <u>SC</u> , <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>2180</u> FEET FROM THE <u>West</u> LINE, SECTION <u>23</u> TOWNSHIP <u>12S</u> RANGE <u>32E</u> NMPM.		10. Field and Pool, or Wildcat East Caprock Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4333' GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

07-10-85
Set 5-1/2" csg @ 10503', 1' off bottom; D.V. tool @ 7008.24'; Float collar @ 10463'. Used 8 centralizers. Cmdt first stage w/1250sx Class "H" 50/50 posmix "A". Drop plug to open D.V. tool. Open D.V. tool, circ hole 6 hrs. Pump 750sx Howco Lite w/15# SAIT/sx + 200sx Class "H"neat. Plug down @ 9:00 a.m. on 7-9-85.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNED <u>Durlene Gunter</u>	TITLE <u>Durlene Gunter-Production Clerk</u> DATE <u>7-16-85</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR	
APPROVED BY _____	TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:	

AUG - 1 1985