

MARTIN YATES, III
1912 - 1985
FRANK W. YATES
1936 - 1986



105 SOUTH FOURTH STREET
ARTESIA, NEW MEXICO 88210
TELEPHONE (505) 748-1471

S. P. YATES
CHAIRMAN OF THE BOARD
JOHN A. YATES
PRESIDENT
PEYTON YATES
EXECUTIVE VICE PRESIDENT
RANDY G. PATTERSON
SECRETARY
DENNIS G. KINSEY
TREASURER

DRILL STEM TEST

REMUDA STATE UNIT #2 - V-2722
660 FNL & 1980 FEL
Sec. 8-T10S-R33E
Lea County, NM

DST #1 4390-4464' (64') SAN ANDRES: TIMES: 30", 60", 60", 120".
RECOVERY: 6' oil, 150' drilling mud (Rw 75 @ 63 F 150000 ppm) +
1512' water (Rw 7 @ 62 F 168000 ppm). SAMPLER: .87 cfg, 2115 cc
oil + 235 cc water) at 580 psi. PRESSURES: IHP 2308, IFP 75.5-494.5,
ISIP 1401.8, 2nd FP 505-804, 2nd SIP 1398, 3rd FP 811-1135, FHP 2295.