

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 31059
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	V-2174
7. Lease Name or Unit Agreement Name	
State "26"	
8. Well No.	4
9. Pool name or Wildcat	Vada (Devonian)
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
4197.8' GR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Western Reserves Oil Company Inc.
3. Address of Operator P. O. Box 993, Midland, TX 79702	4. Well Location Unit Letter F : 2310 Feet From The north Line and 2310 Feet From The west Line Section 26 Township 10S Range 33E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4197.8' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-21-91: MIRUSU & NUBOP. TOH w/SN & 146 jts 2-3/8" tbg. TIH w/4 1/2" CIBP on tbg Set CIBP @ 4560' KB elev. SD for day @ 4:30 pm CST. WO Pool Co. cmt & pump truck.

5-22-91: Circ hole w/10 ppg brine mud w/gel strength of 25 lbs/bbl. Spot 35' cmt plug from 4560'-4525'. TOH w/tbg. NDBOP. Unflange 4 1/2" csg hanger & weld on lift sub. Pull stretch on csg and figure free point at 3100'. Rig up wireline to run free point. Unable to run free point due to short in electric line. SDON.

5-23-91: Rig up wireline & run free point on 4 1/2" csg. Csg free @ 3341', no movement at 3372'. Jet cut pipe at 3357' KB, actual pipe recovered 3340'. Pull & LD 4 1/2" casing. TIH w/tbg to 3410'. Pump 35 sk cmt plug from 3410-3291. SDON & WOC.

(SEE BACK)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Christopher P. Renaud TITLE Engineer DATE 5-29-91
(915)
TYPE OR PRINT NAME Christopher P. Renaud TELEPHONE NO. 683-5533

(This space for State Use)

APPROVED BY Jack Griffin TITLE State Engineer DATE JUL 16 1991
CONDITIONS OF APPROVAL, IF ANY:

WESTERN RESERVES OIL CO. INC.
STATE "26" NO. 4
Unit F, Sec. 26, T10S, R33E
Lea County, NM

PLUG & ABANDONMENT REPORT

5-24-91: Tag cmt plug @ 3286" KB, 3270' GL. Pull & LD tbg to 1950' & spot 100' cmt plug from 1910' - 1810' w/40 sks cmt. LD 2-3/8" tbg. Spot 10 sk cmt plug at surface. Cut off 13 3/8" x 8 5/8" casing head & stack. Weld on flat plate & place NM dry hole marker. Cover up cellar & clean up location.

FINAL REPORT

RECEIVED

MAY 30 1991

HOEL