

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON Governor Jennifer A. Salisbury Cabinet Secretary Lori Wrotenbery Director Oil Conservation Division

November 16, 2000

Samson Resources Company Samson Plaza- Two West Second Tulsa, OK 74103

RE: State BD #3 Unit Letter I, Section 2, Township 12 South, Range 33 East State BD # 1 Unit Letter H, Section 2, Township 12 South, Range 33 East State C A/C 1 # 6 Unit Letter F, Section 2, Township 12 South, Range 33 East

Gentlemen:

Through routine inspection it has come to our attention that the above referenced wells have been shut in for an extended period of time. A review of our records show that these wells have not been Temporarily Abandoned. Order R-9210 states that producing wells can not be shut in for longer than a year.

The following options are available regarding the future disposition of these wells:

- 1. Restore the wells to production.
- 2. Wells to be Temporarily Abandoned in accordance with Rule 203.
- 3. Wells to be Plugged and Abandoned in accordance with Rule 202.

To avoid further action, we request that you exercise one of the above options no later than January 15 ,2001. We request that you notify this office 24 hours prior to any operation in order to witness the operation, either repair or plugging and pressure test upon completion of repairs or to request TXA status.

Very truly yours OIL CONSERVATION DIVISION

Billy Prichard Deputy Inspector, District 1

BP:pc

Xc: Chris Williams Gary Wink Sylvia Dickey File