

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1940, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31411
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No. NM-0202771
7. Lease Name or Unit Agreement Name Apache
8. Well No. 1
9. Pool name or Wildcat Wildcat (San Andres)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ GAS Well ☐ OTHER ☐	
2. Name of Operator Bright & Company	
3. Address of Operator 500 West Texas Ave., Ste. 1280, Midland, Texas 79701	
4. Well Location Unit Letter <u>E</u> : <u>1650</u> Feet From The <u>North</u> Line and <u>990</u> Feet From The <u>West</u> Line Section <u>5</u> Township <u>9S</u> Range <u>34E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>4307.2 GR</u> <u>4321KB</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☒
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 4-20-00 1) Notified NMOCD Sylvia D 2:50PM
4-21-00 2) Spot 30 sx cmt. @ 4730'.
4-24-00 3) Tag TOC @ 4538' Ok'd OCD Billy P.
4) Pressure tested csg. to 200 PSI.
5) Circ. hole w/ MLF.
4-25-00 6) Spot 30 sx cmt. @ 4058'.
4-26-00 7) Tag TOC @ 3898'.
8) Spot 30 sx cmt. 2042-1942'.
9) Spot 30 sx cmt. w/ 2% CaCl @ 434' WOC.
10) Tag TOC @ 330'.
11) Circ. 10 sx cmt. 30' - Surface
12) Cut WH, install dry hole marker, backfill pit & cellar. Cut deadmen.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roger Massey TITLE Area Manager DATE 4-28-00

TYPE OR PRINT NAME Roger Massey TELEPHONE NO. (915) 570-7037

(This space for State Use)

APPROVED BY Billy E. Prueher TITLE GW DATE 4-28-00

CONDITIONS OF APPROVAL, IF ANY: