

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
30-025-31904

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
L-494

7. Lease Name or Unit Agreement Name

State

8. Well No.  
1

9. Pool name or Wildcat  
Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☐ GAS WELL ☐ OTHER ☐ Dry

2. Name of Operator  
Knox Industries, Inc.

3. Address of Operator  
P.O. Box 3023 Midland, TX 79702

4. Well Location  
Unit Letter F : 1929 Feet From The North Line and 2026 Feet From The West Line

Section 2 Township 9-S Range 33-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4342.5 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☒ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☒  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 8730'. 20" conductor pipe set @ 42'. Cement circulated 430' - Set 11jts 13 3/8" 48# csg. w/415 sx. Circulated 200 sx. WOC 16 hrs Tested to 100 PSI (30 min). 4015' - Set 95 jts 8 5/8" csg w/950 sx Western Lite & 200 sx Class "C" with 2% cc. Circulated 88 sx. WOC 15 hrs. Tested to 1000 PSI (30 min). TD @ 8730' with no shows. Called for Plugging Procedure.

7:45 a.m. April 8, 1993 - 1st plug set @8730' - 25 sx Class H. Plug down at 12:00.

2nd plug - Set @ 5600' w/25 sx Class H. Plug down at 2:45 p.m.

3rd plug - Set @ 4000' w/40 sx Class H. Plug down at 4:00 p.m.

4th plug - Set @ 2400' w/35 sx Class H. Plug down at 5:30 p.m.

10 sack plug in top. Welded on plat and marker. Job complete

Filled cellar and cleaned and leveled location. Fenced pits waiting for them to dry.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bruce L. Groce TITLE Production Supervisor DATE 4/16/93

TYPE OR PRINT NAME Bruce L. Groce

TELEPHONE NO. 682-6261

(This space for State Use)

APPROVED BY

Ray W. Wink

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

OIL & GAS INSPECTOR

SEP 20 1993

RECEIVED

JUN 24 1993

AD HOC RS  
SECTION

ON 8 000 000 000 8 100