Submit 3 Copies To Appropriate District	State of New M	exico	-	Form C-103
Office	Energy, Minerals and Natural Resources			Revised March 25, 1999
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	237		WELL API NO.	
District II	T		30-025-33724	
1301 W. Grand Ave., Artesia, NM 88210	tesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type	of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE	🗹 FEE 🗌
District IV	Santa Fe, NM 8	7505	6. State Oil & C	Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM				
87505			7 Y Y	Y1 '
SUNDRY NOTICE	ES AND REPORTS ON WELL	S	7. Lease Name o	r Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSAL DIFFERENT RESERVOIR. USE "APPLICAT	LS TO DRILL OR TO DEEPEN OR PI	OR SLICH		
PROPOSALS.)	HON PORTERWIT (PORM C-101)1	OK BOOM		
1. Type of Well:				
Oil Well Gas Well Other			SV Sunrise State	
2. Name of Operator			7. Well No.	
Concho Oil & Gas Corp.			1	
3. Address of Operator			9. Pool name or Wildcat	
110 W Louisiana, Ste 410, Midland, TX 79701			Echol Devonian NE	
4. Well Location	2175701	L		
4. Well Location				
Unit Letter P : 91	3' feet from the _South	line and 382'	feet fron	n the East line
Omi Letter	loot from the _south_			
Section 15	Township 10S	Range 37E	NMPM	Lea County
	10. Elevation (Show whether L			
•	3740' GL	, , , , , , , , , , , , , , , , , , ,	<b>,</b>	
	propriate Box to Indicate N	Jature of Notice I	Penort or Other	Data
		Nature of Notice, i	COLUMN DE	
NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK 🗍 🛚 F	PLUG AND ABANDON 📋	REMEDIAL WORK	. 📙	ALTERING CASING
TEMPORARILY ABANDON 🔲 (	CHANGE PLANS	COMMENCE DRIL	LING OPNS.	PLUG AND
PULL OR ALTER CASING	MULTIPLE	CASING TEST AN	D 🗆	ABANDONMENT
1 OLL ON METER CO. IO. IO.	COMPLETION	CEMENT JOB		
`	301111 EE 1.1011			
OTHER:		OTHER: Side T	rack Completion	
12. Describe proposed or completed o	pperations. (Clearly state all per	tinent details, and giv	e pertinent dates, i	ncluding estimated date of
starting any proposed work). SEE	RULE 1103. For Multiple Cor	npletions: Attach wel	lbore diagram of p	proposed completion or
recompilation.	11022 1100, 101 112111411	<b>*</b>	1	
5/15/02- MIRU Patterson rig #144. Tes	st BOP to 3000#- Ok.			
5/15/02- Drill cmt to 5472', circ, TOH,	ran csg inspection log.			
5/17/02- Time drill kick off new hole @ 5472'. TIH & wash 35' to btm. Circ.				
5/18/02- Drill & srvy. LD mtr & make up BHA. TIH w/collars.				
5/19/02-Ream thru sidetrack.	<b>F</b>			
5/20/02- Drill & srvy.				
5/29/02- TOH, TIH, W&R to btm starti	ing at KOP & resume drlg.			
6/5/02- Run Gyro Srvy.	g		<i>y.</i>	
6/6/02- Drill & srvy to 10,848'.			$f_{i}$	
7/1/02- RU csg crew & ran 5 ½" csg &	set @ 10.848' Cmt csg in two	stages as follows: 1s	t stage-20 BFWS 8	thead cmt w/650 sxs
50/50/10 Poz H gel + additivit	tes, tail w/750 sxs 50/50/2 Poz H	I gel + additives. Dro	op opening bomb.	open DVT @ 5390' w/1400
nei Circ 52 eys cmt off DVT	Circ. 2 <sup>nd</sup> stage-20 BFWS ahea	ad cmt w/450 61:15:1	1 Class C Poz CSI	E + additives. ND BOP &
NII Clean & jet nit RDMO	WO rig to deepen well to Dev	onian.	/3	
7/20/02- MIRU Key #482. Drill 4 3/4" h			N.	
*See Attached	1010 10 20 01111111		No. of the second	
I hereby certify that the information about	ove is true and complete to the l	est of my knowledge	and belief	
		cot of my knownedge	una contra	
SIGNATURE ZOOR Kusta	m to TITLE	Production Analys	t DAT	E 9/3/02
SIGNATURE NEW IX PLISTON	many IIIEL	1 Todaction 7 thanys	·	<u> </u>
Type or print name Dora Bustamant	re.	-	Telephone No. 91	5-683-7443
-71	<u>~</u>	100		
(This space for State use)	F.			
	<b></b> }	PATH F MONED B		1111 2 W C 00
A DDDD OVED DV	<b>गागांज</b> ा			DATE J/H 1 7 203
APPPROVED BY Conditions of approval, if any:	TITLE_[]	PAUL F. KAUTZ POLEUM ENGINEE		DATE J/H 1 7 203

C