

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-33755
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	VA-0492
7. Lease Name or Unit Agreement Name	Sawyer AQN State
8. Well No.	2
9. Pool name or Wildcat	Sawyer San Andres, West

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION	3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter <u>A</u> : <u>810</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>6</u> Township <u>10S</u> Range <u>37E</u> NMPM <u>Lea</u> County <u></u>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3984' GR			

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Perforate & acidize <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-13-97 - Cleaned location, set and tested anchor. Moved in and rigged up pulling unit. Rigged up wireline. TIH with logging tools and ran CNL/CBL/GR/CCL log. TOOH with logging tools and rigged down wireline.
3-14-97 - Nippled up BOP and tested. TIH with bit, scraper and 2-7/8" tubing. Tagged PBTD at 5024'. TOOH with bit, scraper and tubing. Rigged up wireline. TIH with 4" casing guns and perforated 4900-4954' w/15 .42" holes as follows: 4900, 01, 02, 04, 06, 08, 10, 16, 17, 25, 26, 45, 46, 53 & 4954' (1 SPF - San Andres). TOOH with casing guns and rigged down wireline. TIH with packer and tubing. Set packer at 4844'. Nippled down BOP. Nippled up wellhead. Acidized perforations 4900-4954' with 4000 gallons 15% double inhibited iron control HCL acid. Swabbing.
3-15-97 - Swabbing.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Operations Technician DATE March 19, 1997
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY
GARY WINK
FIELD REP. II

MAR 20 1997

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

