ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

POST OFFICE BOX 1980 HOBBS, NEW MEXICO 88241-1980 (505) 393-6161

July 24, 1997

vary 2., 1777	
Cobra Oil & Gas Corp	
P 0 Box 8206 ATT: Rory Edwards	
Wichita Falls, TX 76307	
Gentlemen:	
Gentiemen.	
Form C-103, Report of Plugging, for your State 16 #1-P 16-9s	
cannot be approved until a Division representative has made an inspection of the l	ocation and
found it to be cleared to comply with Division Rules and Regulations. Please chec the space provided to indicate that the work has been done.	ok each hem m
the space provided to maidule that the work has been done.	
() 1. All pits have been filled and leveled	•••
() 2. Rat hole and cellar have been filled and leveled.	haan set in
() 3. A steel marker 4" in diameter and approximately 4' above ground level has concrete. It must show the <u>OPERATOR</u> , <u>LEASE NAME</u> , <u>WELL NUME</u>	
quarter/QUARTER SECTION OR UNIT LETTER DESIGNATION, SE	
TOWNSHIP, AND RANGE, AND API NUMBER which have been perro	
stenciled or welded on the marker.	
() 4. The location has been leveled as nearly as possible to original top ground of	contour and has
been cleared of al junk and equipment. () 5. The dead men and tie downs have been cut and removed.	
() 6. If a one-well lease or last remaining well on lease, the battery and burn pit	locations have
been leveled and cleared of all junk and equipment.	
The above are minimum requirements and no plugging bond will be released until plugged and abandoned wells have been inspected and Form C-103 approved. When work outlined above has been done, please notify this office by filling in the blank returning this letter to us so that our representative will not have to make more that the location.	hen all of the form below and
Very truly yours,	
OIL CONSERVATION DIVISION	
Mis Welliams	
Chris Williams; Supervisor, District I	
DOD 1020	
FILL IN BELOW AND RETURN TO: Oil Conservation Division, POBox 1980	
Hobbs NM 88241 I certify that the above work has been done and the well referenced above is ready	for your
inspection and approval.	•
PERATOR NAME & TITLE	DATE