

AUG 23 1999

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-34328
Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No. VA-8888
Lease Name or Unit Agreement Name Bryce State
Well No. 1
Pool name or Wildcat Sawyer, San Andres, West

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
Name of Operator Marbob Energy Corporation	
Address of Operator P.O. Box 227, Artesia, N M 88210	
Well Location Unit Letter <u>C</u> : <u>990</u> Feet From The <u>North</u> Line and <u>1800</u> Feet From The <u>West</u> Line Section <u>2</u> Township <u>10S</u> Range <u>37E</u> NMPM <u>Lea</u> County	
Elevation (Show whether DF, RKB, RT, GR, etc.)	

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 8-11-99 Set 5 1/2 CIBP @ 4900' dump bailed 4 sx. cmt. on top
- 8-12-99 circulate hole w/ 9.8# mud
- 8-12-99 spot 20 sx. class "C" neat cmt. @ 4342' to 4145'
- 8-12-99 spot 20 sx. class "C" neat cmt. @ 2958' to 2761'
- 8-16-99 cut & pull 5 1/2 casing @ 2340' circulate hole w/ 9.8# mud
- 8-16-99 spot 40 sx. class "C" neat cmt. @ 2392' woc 4hrs. tag plug @ 2282'
- 8-17-99 spot 40 sx. class "C" neat cmt. @ 575' woc 4hrs. tag plug @ 445'
- 8-17-99 circulate well w/ 20 sx. class "C" neat cmt. from 30' to surface
- 8-18-99 cut off well head weld on plate install dry hole marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE B. M. T. S. TITLE Agent DATE 8/20/99

TELEPHONE NO.

APPROVED BY Billy P. ... TITLE ... DATE ...

COPIES OF APPROVAL (IF ANY)

JC GWW

no

NSW-4117 440N & 1800W San Andres
80.10 ac E/2 NW/4

MAR 03 1998

JUN 03 1999