District Office	Energy, Minerals and Natural Re	exico esources Department	Form C-103 Revised 1-1-89
to Appropriate District Office DISTRICT I	OIL CONSERVATIO	N DIVISION	WELL API NO.
P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 P.O. Box 2088		30-025-34862	
DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 DISTRICT III DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410		5. Indicate Type of Lease STATE X FEE	
		6. State Oil & Gas Lease No. V-4834	
	TICES AND REPORTS ON WEL		
DIFFERENT RESE (FORM	ROPOSALS TO DRILL OR TO DEEPEN ERVOIR. USE "APPLICATION FOR PEI C-101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A RMIT	7. Lease Name or Unit Agreement Name
I. Type of Well: OIL OAS WELL X	CTHER		East Sand Springs Unit
2. Name of Operator			8. Well No.
YATES PETROLEUM CORPO 3. Address of Operator			2 9. Pool name or Wildcat
105 South 4th St., Ar	tesia, NM 88210		Wildcat Mississippian
I. Well Location Unit LetterN:66	0 Feet From The South	Line and170	0 Feet From The West Line
0.4			NMPM Lea County
Section 24	10. Elevation (Show whether	DF, RKB, RT, GR, etc.)	
		3' GR	
II. Check NOTICE OF IN	Appropriate Box to Indicate I		SEQUENT REPORT OF:
	CHANGE PLANS		
ULL OR ALTER CASING		CASING TEST AND CE	
THER:		OTHER: <u>Spud</u> , co surface	nductor, resume drilling,
12. Describe Proposed or Completed Ope work) SEE RULE 1103.	rations (Clearly state all pertinent details, an	nd give pertinent dates, inclu	ding estimated date of starting any proposed
Spudded a 26" hole wi 40' of 20" conductor spud via voice mail.	pipe. Cemented to surf	11:00 AM <u>1-28-2</u> ace. NOTE: No 3/4" hole with	000. Drilled to 40' and set tified Sylvia w/OCD-Hobbs of rotary tools at 3:00 AM 2-6-2000
Spudded a 26" hole wi 40' of 20" conductor spud via voice mail. NOTE: Notified Sylvi TD 428'. Reached TD casing set at 428'. 1 Cemented with 280 sac 2-6-2000. Bumped plu flow nipple. Drilled	pipe. Cemented to surf Resumed drilling a 14- ta w/OCD-Hobbs of intent at 9:00 AM 2-6-2000. R L-Texas Pattern notched cks PremiumPlus with 2% ig to 400 psi, OK. Circ l out at 9:45 AM 2-7-200 Lling. NOTE: Notified	11:00 AM <u>1-28-2</u> ace. NOTE: No 3/4" hole with to resume dril an 10 joints of guide shoe set CaC12 (yield 1. ulated 60 sacks 0. WOC 20 hour	000. Drilled to 40' and set tified Sylvia w/OCD-Hobbs of rotary tools at 3:00 AM 2-6-2000 ling via voice mail. 11-3/4" 42# H-40 (433.86') of
Spudded a 26" hole wi 40' of 20" conductor spud via voice mail. NOTE: Notified Sylvi TD 428'. Reached TD casing set at 428'. I Cemented with 280 sac 2-6-2000. Bumped plu flow nipple. Drilled to 11". Resumed dril and cement via voice	pipe. Cemented to surf Resumed drilling a 14- ia w/OCD-Hobbs of intent at 9:00 AM 2-6-2000. R L-Texas Pattern notched cks PremiumPlus with 2% ig to 400 psi, OK. Circ i out at 9:45 AM 2-7-200 Lling. NOTE: Notified mail.	11:00 AM <u>1-28-2</u> ace. NOTE: No 3/4" hole with to resume dril an 10 joints of guide shoe set CaC12 (yield 1. ulated 60 sacks 0. WOC 20 hour Sylvia w/OCD-Ho	000. Drilled to 40' and set tified Sylvia w/OCD-Hobbs of rotary tools at 3:00 AM 2-6-2000 ling via voice mail. 11-3/4" 42# H-40 (433.86') of at 428'. Insert float set at 38 34, weight 14.8). PD 1:40 PM . WOC. Cut off and welded on s and 5 minutes. Reduced hole
Spudded a 26" hole wi 40' of 20" conductor spud via voice mail. NOTE: Notified Sylvi TD 428'. Reached TD casing set at 428'. I Cemented with 280 sac 2-6-2000. Bumped plu flow nipple. Drilled to 11". Resumed dril and cement via voice	pipe. Cemented to surf Resumed drilling a 14- ia w/OCD-Hobbs of intent at 9:00 AM 2-6-2000. R L-Texas Pattern notched cks PremiumPlus with 2% ig to 400 psi, OK. Circ d out at 9:45 AM 2-7-200 Lling. NOTE: Notified mail.	11:00 AM <u>1-28-2</u> ace. NOTE: No 3/4" hole with to resume dril an 10 joints of guide shoe set CaCl2 (yield 1. ulated 60 sacks 0. WOC 20 hour Sylvia w/OCD-Ho	000. Drilled to 40' and set tified Sylvia w/OCD-Hobbs of rotary tools at 3:00 AM 2-6-2000 ling via voice mail. 11-3/4" 42# H-40 (433.86') of at 428'. Insert float set at 38 34, weight 14.8). PD 1:40 PM . WOC. Cut off and welded on s and 5 minutes. Reduced hole bbs of intent to run casing
Spudded a 26" hole wi 40' of 20" conductor spud via voice mail. NOTE: Notified Sylvi TD 428'. Reached TD casing set at 428'. I Cemented with 280 sac 2-6-2000. Bumped plu flow nipple. Drilled to 11". Resumed dril and cement via voice	pipe. Cemented to surf Resumed drilling a 14- ia w/OCD-Hobbs of intent at 9:00 AM 2-6-2000. R L-Texas Pattern notched cks PremiumPlus with 2% ig to 400 psi, OK. Circ d out at 9:45 AM 2-7-200 Lling. NOTE: Notified mail.	11:00 AM <u>1-28-2</u> ace. NOTE: No 3/4" hole with to resume dril an 10 joints of guide shoe set CaCl2 (yield 1. ulated 60 sacks 0. WOC 20 hour Sylvia w/OCD-Ho	000. Drilled to 40' and set tified Sylvia w/OCD-Hobbs of rotary tools at 3:00 AM 2-6-2000 ling via voice mail. 11-3/4" 42# H-40 (433.86') of at 428'. Insert float set at 38 34, weight 14.8). PD 1:40 PM . WOC. Cut off and welded on s and 5 minutes. Reduced hole bbs of intent to run casing
Spudded a 26" hole wi 40' of 20" conductor spud via voice mail. NOTE: Notified Sylvi TD 428'. Reached TD casing set at 428'. J Cemented with 280 sac 2-6-2000. Bumped plu flow nipple. Drilled to 11". Resumed dril and cement via voice	pipe. Cemented to surf Resumed drilling a 14- ia w/OCD-Hobbs of intent at 9:00 AM 2-6-2000. R L-Texas Pattern notched cks PremiumPlus with 2% ig to 400 psi, OK. Circ d out at 9:45 AM 2-7-200 Lling. NOTE: Notified mail.	11:00 AM <u>1-28-2</u> ace. NOTE: No 3/4" hole with to resume dril an 10 joints of guide shoe set CaCl2 (yield 1. ulated 60 sacks 0. WOC 20 hour Sylvia w/OCD-Ho	000. Drilled to 40' and set tified Sylvia w/OCD-Hobbs of rotary tools at 3:00 AM 2-6-2000 ling via voice mail. 11-3/4" 42# H-40 (433.86') of at 428'. Insert float set at 38 34, weight 14.8). PD 1:40 PM . WOC. Cut off and welded on s and 5 minutes. Reduced hole bbs of intent to run casing
Spudded a 26" hole wi 40' of 20" conductor spud via voice mail. NOTE: Notified Sylvi TD 428'. Reached TD casing set at 428'. J Cemented with 280 sac 2-6-2000. Bumped plu flow nipple. Drilled to 11". Resumed dril and cement via voice	pipe. Cemented to surf Resumed drilling a 14- ia w/OCD-Hobbs of intent at 9:00 AM 2-6-2000. R L-Texas Pattern notched cks PremiumPlus with 2% ig to 400 psi, OK. Circ l out at 9:45 AM 2-7-200 lling. NOTE: Notified mail.	11:00 AM <u>1-28-2</u> ace. NOTE: No 3/4" hole with to resume dril an 10 joints of guide shoe set CaC12 (yield 1. ulated 60 sacks 0. WOC 20 hour Sylvia w/OCD-Ho belief.	000. Drilled to 40' and set tified Sylvia w/OCD-Hobbs of rotary tools at 3:00 AM 2-6-2000 ling via voice mail. 11-3/4" 42# H-40 (433.86') of at 428'. Insert float set at 38 34, weight 14.8). PD 1:40 PM . WOC. Cut off and welded on s and 5 minutes. Reduced hole bbs of intent to run casing
Spudded a 26" hole wi 40' of 20" conductor spud via voice mail. NOTE: Notified Sylvi TD 428'. Reached TD casing set at 428'. I Cemented with 280 sac 2-6-2000. Bumped plu flow nipple. Drilled to 11". Resumed dril and cement via voice Ihereby certify the the information above into skonature TYPE OR FRINT NAME Rusty Klei	pipe. Cemented to surf Resumed drilling a 14- ia w/OCD-Hobbs of intent at 9:00 AM 2-6-2000. R L-Texas Pattern notched cks PremiumPlus with 2% ig to 400 psi, OK. Circ d out at 9:45 AM 2-7-200 lling. NOTE: Notified mail.	11:00 AM <u>1-28-2</u> ace. NOTE: No 3/4" hole with to resume dril an 10 joints of guide shoe set CaC12 (yield 1. ulated 60 sacks 0. WOC 20 hour Sylvia w/OCD-Ho belief.	000. Drilled to 40' and set tified Sylvia w/OCD-Hobbs of rotary tools at 3:00 AM 2-6-2000 ling via voice mail. 11-3/4" 42# H-40 (433.86') of at 428'. Insert float set at 38 34, weight 14.8). PD 1:40 PM . WOC. Cut off and welded on s and 5 minutes. Reduced hole