Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

			•		
OII	CONSER	VAT	TON	DIVIS	ION

DISTRICT 1 P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATIO		WELL API NO.		
	P.O. Box 208		30-025-34989		
P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico	5. Indicate Type of Lease STATE X FEU			
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 8741)			6. State Oil & Gas Lease No. V-4583		
( DO NOT USE THIS FORM FOR IPRO DIFFERENT REBER (FORM C	ICES AND REPORTS ON WEL OPOSALS TO DRILL OR TO DEEPEN RVOIR. USE "APPLICATION FOR PER -101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name		
i. Type of Well:  OIL  WELL  WELL  GAS  WELL  X	OTHER	ı	Shinnery Unit		
2. Name of Operator YATES PETROLEUM CORPOR			8. Well No.		
3. Address of Operator		i	9. Pool name or Wildcat		
105 South 4th St., Art	esia, NM 88210		Wildcat Mississippian		
4. Well Location  Unit Letter D: 660	Feet From The North	Line and 735	Feet From The West Line		
Section 9	Township 10S Ra 10. Elevation (Show whether 423	nge 34E DF, RKB, RT, GR, etc.) 9' GR	NotPM Lea County		
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF					
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	G OPNS. PLUG AND ABANDONMENT		
PULL OR ALTER CASING		CASING TEST AND C			
OTHER:		OTHER: Production casing & cement X			
work) SEE RULE 1103.			cling estimated date of starting any proposed		
follows: 5 joints of blasted (146.07'); 8 P-110 sandblasted (90 7" 26# P-110 sandblas (Total 13244.62') of 13190'. Bottom of ma sacks Poz H (65-35-6)	7" 29# P-110 sandblast joints of 7" 26# P-110 4.54'); 53 joints of 7' ted (126.40') and 208 5 casing set at 13232'. rker set at 12900'. To, 6% gel, .6% FL52 (yield, .6% FL25 and 5#/sack plug to 2950 psi for 1	varnished (367 varnished (367 26# P-110 varnished (367 Float shoe set op of marker seeld 1.99, weigh gilsonite (vie	ts of 7" 29# & 26# casing as 4 joints of 7" 26# P-110 sand15'); 22 joints of 7" 26# nished (2498.92'); 3 joints of # P-110 varnished (8995.10') at 13232'. Float collar set at t at 12879'. Cemented with 500 t 12.4). Tailed in with 900 ld 1.64, weight 13.0). PD 8:00 laced casing with fresh water.		
Waiting on completion	, unit.				
	ne and complete to the best of my knowledge and	belief.			
SIGNATURE TUSTINT	lin m	Operations 1	Technician pare Feb. 15, 2001		
TYPEOR PRINT NAME Rusty Klei	n		<u>тешенноме мо. 505/748—1</u> 47		
(This space for State Use)		ç in o'r	51. AAA		
	π	C 10	MAY 0 1 2001		
APPROVED BY					

CONDITIONS OF APPROVAL, IF ANY: