

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

**CONFIDENTIAL**

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30025-35597
1. Type of Well Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> Injection <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Concho Oil & Gas Corp.		6. State Oil & Gas Lease No. V4674
3. Address of Operator 110 W. Louisiana Ste 410; Midland, Tx 79701		7. Lease Name or Unit Agreement Name: Sundown State
4. Well Location Unit Letter <u>M</u> : <u>660</u> Feet from the <u>South</u> line and <u>660</u> feet from the <u>West</u> line Section <u>14</u> Township <u>10S</u> Range <u>37E</u> NMPM Lea County		7. Well No. 2
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3940 GL		8. Pool name or Wildcat Undes. San Andres

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  
**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**  
REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: completion ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

12-26-01 Tag PBTD @ 5102'.  
12-27-01 TOC @ 1364'. Perf @ 4996-5010' w/ 2 SPF (29 holes). RU swab.  
12-28-01 Acidize perfs @ 4996-5010' w/ 1000 gals 15% NEFE 9010 acid w/ 45 BS. RU Swab.  
01-03-02 Acidize perfs @ 4996-5010' w/ 5000 gals 15% NEFE 9010 w/ 30 GPT anti sludge solvent, 20 GPT FE 300, FE 301, FE 40, & 60 BS.  
01-07-02 RIH & set tbg @ 5053'. RU swab.  
01-08-02 RIH w/ rods & pump.  
01-09-02 Set pumping unit.  
01-16-02 IP: 47 BO, 250 BW, & 15 MCF.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terri Stathem TITLE Production Analyst DATE 1-17-01

Type or print name Terri Stathem Telephone No. 915/683-7443

(This space for State use)

APPROVED BY \_\_\_\_\_ TITLE PAUL F. RABIZ DATE JAN 25 2002  
Conditions of approval, if any: