

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
LC-062178	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- WIW	7. Unit Agreement Name Milnesand Unit
2. Name of Operator Breck Operating Corp.	8. Farm or Lease Name
3. Address of Operator P.O. Box 911, Breckenridge, Texas 76024	9. Well No. 151
4. Location of Well UNIT LETTER <u>N</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>12</u> TOWNSHIP <u>8-S</u> RANGE <u>34-E</u> NMPM.	10. Field and Pool, or Wildcat Milnesand (San Andres)
15. Elevation (Show whether DF, RT, GR, etc.) 4249' GR	12. County Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The above mentioned will is plugged and abandoned, and the well site is ready for final inspection. The plugs were placed as follows:

1. 25 sx 4600-4257'-Top of plug tagged.
2. 60 sx 465-327'-4½" casing shot @ 465' and pulled. Top of plug tagged.
3. 10 sx 30-3'-Cement circulated. Cut 8 5/8" 3' below surface and welded on steel plate.

Hole loaded with brine and salt gel.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Kevin G. Duncan</u>	TITLE <u>Petroleum Engineer</u>	DATE <u>5-11-87</u>
OIL & GAS INSPECTOR		
APPROVED BY <u>Jack Griffin</u>	TITLE _____	DATE <u>JUL 8 1987</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

MAY 13 1987

OCD
HOBBS OFFICE