

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOBBS OFFICE O. G. C.
NEW MEXICO OIL CONSERVATION COMMISSION
Mar 7 11 38 AM '66

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
Atlantic State	
9. Well No.	
4	
10. Field and Pool, or Wildcat	
Allison Penn	
12. County	
Roosevelt	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	
2. Name of Operator	
Sam Boren	
3. Address of Operator	
Box 953, Midland, Texas	
4. Location of Well	
UNIT LETTER <u>J</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM	
THE <u>East</u> LINE, SECTION <u>32</u> TOWNSHIP <u>8S</u> RANGE <u>37E</u> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	
GL 4024	

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Plugged 2/18/66. (pipe collapsed 12/12/62) cement plug 6380-6509. Pumped 25 sax down 7-5/8" csg. to 4200'. 7-5/8 shoe @ 4246'. 7-5/8" csg. shot @ 1325, pumped 25 sax down 7-5/8" csg. 10-3/4 shoe @ 417', pumped 25 sax down 7 5/8" csg. @ 440. 10 sax in top of 10-3/4" casing. Steel marker erected. Will notify when ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ernest Smith TITLE Agent DATE March 1, 1966

APPROVED BY Leslie A. Clement TITLE DATE March 1, 1966

CONDITIONS OF APPROVAL, IF ANY:

HOBBES OFFICE 2880H

2880H 2880H 2880H