JF COPIES RE							
			····		-		
DISTRIBUT	ION	 	NEW MEXICO OIL C	ONSERVATION COM	MIS. JN	Form C-104	
ANTA FE		_	REQUEST	FOR ALLOWABLE			C-104 and C+1.
FILE		1		AND		Effective 1-1-6	5
U.S.G.S.		AU1	THORIZATION TO TRA	NSPORT OIL AND	NATURAL G	AS	
LAND OFFICE							
TRANSPORTER	GAS						
OPERATOR							
PRORATION OF	TICE						
Operator							
M &	W OPERATI	NGCOMPANY					
Address							
P.0.	BOX 922	, LOVINGTO	N, NEW MEXICO 882	6 0			
Reason(s) for filing				Other (Pleas	se explain)		
New Well		Chang	ge in Transporter of:				
Recompletion		Oil	Dry Ga	s			
Change in Ownersh	ı D	Casin	ghead Gas Conder	sate			
If change of owner and address of pre	evious owner_		PETROLEUM CORPORAT	ION, 1113 AMERI	CANA BLDG.	HOUSTON, TEXAS	77002
Lease Name	OF WELL A	Well	No. Pool Name, Including F	ormation	Kind of Lease		Lease No.
HAYES FEDE	ALL.	1	ALLISON PENN		State, Federal	or Fee FEDERAL	NM-03586
Location				·			-1
Unit Letter	; _=	1950 / Feet	From The SOUTH Lin	e and	Feet From T	EAST	
Line of Section	30	Township	85 Range	378 , NMP	M, ROOSI	EVELT	County
DESIGNATION	OF TRANSP	ORTER OF C	OIL AND NATURAL GA	S			
Name of Authorized THE PERMIA			or Condensate	Address (Give address		ed cons of this form is t	
		LTON		P.O. BOX 3119,			obesent)
Name of Authorized			s 🚺 or Dry Gas 🗀		MIDLAND,		·
Name of Authorized	d Transporter o	f Casinghead Ga	s or Dry Gas	Address (Give address	MIDLAND, to which approve	MEXAS 79701	,
CITIES SER	Transporter of	f Casinghead Ga	s or Dry Gas		MIDLAND, to which approve OKLAHOMA	TEXAS 79701 ed copy of this form is t	,
CITIES SER	Transporter of VICE OIL C	f Casinghead Ga	Sec. Twp. Rge.	Address (Give address BARTLESVILLE, Is gas actually connect	MIDLAND, to which approve OKLAHOMA	TEXAS 79701 ed copy of this form is t	·
CITIES SER	d Transporter of VICE OIL C. l or liquids, his. is commingled	f Casinghead Ga COMPANY Unit J		BARTLESVILLE, Is gas actually connect YES	midiand, to which approve OKLAHOMA	TEXAS 79701 ed copy of this form is t	,
CITIES SER If well produces of give location of tar If this production COMPLETION I	d Transporter of VICE OIL C 1 or liquids, nl:s. is commingled DATA	f Casinghead Ga COMPANY Unit J d with that from	Sec. Twp. Rge. 30 85 37E	BARTLESVILLE, Is gas actually connect YES	to which approve OKLAHOMA ted? When when ten number:	TEXAS 79701 ed copy of this form is t	o be sent)
CITIES SER	d Transporter of VICE OIL C 1 or liquids, nl:s. is commingled DATA	f Casinghead Ga COMPANY Unit J d with that from	Sec. Twp. Rge. 30 85 37E any other lease or pool,	Address (Give address BARTLESVILLE, Is gas actually connect YES give commingling ord	to which approve OKLAHOMA ted? When ted?	TEXAS 79701 ed copy of this form is to the copy of the co	o be sent)
CITIES SER If well produces of give location of tai f this production COMPLETION I Designate Ty	d Transporter of VICE OIL C 1 or liquids, nl:s. is commingled DATA	f Casinghead Ga COMPANY Unit J d with that from	Sec. Twp. Rge. 30 85 378 n any other lease or pool, Oil Well Gas Well	Address (Give address BARTLESVILLE, Is gas actually connect YES give commingling ord New Well Workover	to which approve OKLAHOMA ted? When ted?	TEXAS 79701 ed copy of this form is to the copy of the co	o be sent)
CITIES SER If well produces of give location of tar f this production COMPLETION I	d Transporter of VICE OIL C 1 or liquids, nl:s. is commingled DATA	f Casinghead Ga COMPANY Unit J d with that from	Sec. Twp. Rge. 30 85 37E any other lease or pool,	Address (Give address BARTLESVILLE, Is gas actually connect YES give commingling ord	to which approve OKLAHOMA ted? When ted?	PEXAS 79701 Id copy of this form is to the copy of th	o be sent)
CITIES SER If well produces of give location of tar f this production COMPLETION I Designate Ty Date Spudded	d Transporter of VICE OIL C l or liquids, nl:s. is commingled DATA ype of Complete	f Casinghead Ga COMPANY Unit J d with that from letion — (X)	Sec. Twp. Rge. 30 85 37E n any other lease or pool, Oil Well Gas Well ol. Ready to Prod.	Address (Give address RARTLESVILLE, Is gas actually connect YES give commingling ord New Wel. Workover Total Depth	to which approve OKLAHOMA ted? When ted?	PEXAS 79701 Id copy of this form is to the copy of th	o be sent)
CITIES SER If well produces of give location of tar f this production COMPLETION I Designate Ty Date Spudded	d Transporter of VICE OIL C l or liquids, nl:s. is commingled DATA ype of Complete	f Casinghead Ga COMPANY Unit J d with that from letion — (X)	Sec. Twp. Rge. 30 85 378 n any other lease or pool, Oil Well Gas Well	Address (Give address BARTLESVILLE, Is gas actually connect YES give commingling ord New Well Workover	to which approve OKLAHOMA ted? When ted?	10-3-61 Plug Back Same Res	o be sent)
CITIES SER If well produces of give location of tal f this production COMPLETION I Designate Ty Date Spudded Elevations (DF, RI	d Transporter of VICE OIL C l or liquids, nl:s. is commingled DATA ype of Complete	f Casinghead Ga COMPANY Unit J d with that from letion — (X)	Sec. Twp. Rge. 30 85 37E n any other lease or pool, Oil Well Gas Well ol. Ready to Prod.	Address (Give address RARTLESVILLE, Is gas actually connect YES give commingling ord New Wel. Workover Total Depth	to which approve OKLAHOMA ted? When ted?	PEXAS 79701 Id copy of this form is to the copy of th	o be sent)
CITIES SER If well produces of give location of tar f this production COMPLETION I Designate Ty Date Spudded	d Transporter of VICE OIL C l or liquids, nl:s. is commingled DATA ype of Complete	f Casinghead Ga COMPANY Unit J d with that from letion — (X)	Sec. Twp. Rge. 30 85 37E n any other lease or pool, Oil Well Gas Well ol. Ready to Prod.	Address (Give address RARTLESVILLE, Is gas actually connect YES give commingling ord New Wel. Workover Total Depth	to which approve OKLAHOMA ted? When ten number:	10-3-61 Plug Back Same Res	o be sent)
CITIES SER If well produces of give location of tal f this production COMPLETION I Designate Ty Date Spudded Elevations (DF, RI	d Transporter of VICE OIL C l or liquids, nl:s. is commingled DATA ype of Complete	f Casinghead Ga COMPANY Unit J d with that from letion — (X)	Sec. Twp. Rge. 30 85 376 n any other lease or pool, Oil Well Gas Well oil Ready to Prod. roducing Formation	Address (Give address RARTLESVILLE, Is gas actually connect YES give commingling ord New Wel. Workover Total Depth Top Oil/Gas Pay	to which approve OKLAHOMA ted? When the pumber: Deepen	PEXAS 79701 Id copy of this form is to the copy of th	o be sent)
If well produces of give location of tar of this production COMPLETION I Designate Ty Date Spudded Elevations (DF, RI Perforations	d Transporter of VICE OIL C l or liquids, ml:s. is commingled DATA ype of Comple K3, RT, GR, etc.	f Casinghead Ga COMPANY Unit J d with that from letion — (X) Date Comp	Sec. Twp. Rge. 30 85 37E n any other lease or pool, Oil Well Gas Well ol. Ready to Prod. TUBING, CASING, AND	Address (Give address RARTLESVILLE, Is gas actually connect YES give commingling ord New Wel. Workover Total Depth Top Oil/Gas Pay	MIDIAND, 'I to which approve OKLAHOMA ted? When prove the second of th	10-3-61 Plug Back Same Res P.B.T.D. Tubing Depth Depth Casing Shoe	o be sent)
CITIES SERVING Well produces of give location of tar for this production COMPLETION IDESIGNATE TO Date Spudded Elevations (DF, RI	d Transporter of VICE OIL C l or liquids, nl:s. is commingled DATA ype of Complete	f Casinghead Ga COMPANY Unit J d with that from letion — (X) Date Comp	Sec. Twp. Rge. 30 85 376 n any other lease or pool, Oil Well Gas Well oil Ready to Prod. roducing Formation	Address (Give address RARTLESVILLE, Is gas actually connect YES give commingling ord New Wel. Workover Total Depth Top Oil/Gas Pay	MIDIAND, 'I to which approve OKLAHOMA ted? When prove the second of th	PEXAS 79701 Id copy of this form is to the copy of th	o be sent)
CITIES SERVING Well produces of give location of tar for this production COMPLETION IDESIGNATE TO Date Spudded Elevations (DF, RI	d Transporter of VICE OIL C l or liquids, ml:s. is commingled DATA ype of Comple K3, RT, GR, etc.	f Casinghead Ga COMPANY Unit J d with that from letion — (X) Date Comp	Sec. Twp. Rge. 30 85 37E n any other lease or pool, Oil Well Gas Well ol. Ready to Prod. TUBING, CASING, AND	Address (Give address RARTLESVILLE, Is gas actually connect YES give commingling ord New Wel. Workover Total Depth Top Oil/Gas Pay	MIDIAND, 'I to which approve OKLAHOMA ted? When prove the second of th	10-3-61 Plug Back Same Res P.B.T.D. Tubing Depth Depth Casing Shoe	o be sent)
CITIES SERVING Well produces of give location of tar for this production COMPLETION IDESIGNATE TO Date Spudded Elevations (DF, RI	d Transporter of VICE OIL C l or liquids, ml:s. is commingled DATA ype of Comple K3, RT, GR, etc.	f Casinghead Ga COMPANY Unit J d with that from letion — (X) Date Comp	Sec. Twp. Rge. 30 85 37E n any other lease or pool, Oil Well Gas Well ol. Ready to Prod. TUBING, CASING, AND	Address (Give address RARTLESVILLE, Is gas actually connect YES give commingling ord New Wel. Workover Total Depth Top Oil/Gas Pay	MIDIAND, 'I to which approve OKLAHOMA ted? When prove the second of th	10-3-61 Plug Back Same Res P.B.T.D. Tubing Depth Depth Casing Shoe	o be sent)
CITIES SERVING MEDICAL SERVING	d Transporter of VICE OIL C l or liquids, mls. is commingled DATA yoe of Comple K3, RT, GR, etc.	f Casinghead Ga COMPANY Unit J d with that from letion — (X) Date Comp	Sec. Twp. Rge. 30 85 37E n any other lease or pool, Oil Well Gas Well ol. Ready to Prod. TUBING, CASING, AND	Address (Give address RARTLESVILLE, Is gas actually connect YES give commingling ord New Wel. Workover Total Depth Top Oil/Gas Pay	MIDIAND, 'I to which approve OKLAHOMA ted? When prove the second of th	10-3-61 Plug Back Same Res P.B.T.D. Tubing Depth Depth Casing Shoe	o be sent)
If well produces of give location of tar of this production COMPLETION I Designate Ty Date Spudded Elevations (DF, RI Perforations	d Transporter of VICE OIL C l or liquids, mls. is commingled DATA yoe of Comple K3, RT, GR, etc.	f Casinghead Ga COMPANY Unit J d with that from letion — (X) Date Comp	Sec. Twp. Rge. 30 85 37E n any other lease or pool, Oil Well Gas Well oil Ready to Prod. TOURING Formation TUBING, CASING, AND ING & TUBING SIZE	RARTLESVILLE, Is gas actually connect TES give commingling ord New Wel. Workover Total Depth Top Oil/Gas Pay CEMENTING RECO DEPTH:	MIDIAND, 'to which approve OKLAHOMA Ited? When the prove of the provention of the p	PEXAS 79701 ad copy of this form is to 10-3-61 Plug Back Same Res P.B.T.D. Tubing Depth Depth Casing Shoe	o be sent)
CITIES SER If well produces of give location of tar f this production COMPLETION I Designate Ty Date Spudded Elevations (DF, RI Perforations	d Transporter of VICE OIL C l or liquids, nl:s. is commingled DATA yoe of Comple K.3, RT, GR, en	f Casinghead Ga COMPANY Unit J d with that from letion — (X) Date Comp co., Name of P	Sec. Twp. Rge. 30 85 37E n any other lease or pool, Oil Well Gas Well ol. Ready to Prod. TUBING, CASING, AND ING & TUBING SIZE	Address (Give address RARTLESVILLE, Is gas actually connect YES give commingling ord New Wel. Workover Total Depth Top Oil/Gas Pay CEMENTING RECO DEPTH:	MIDIAND, to which approve OKLAHOMA Ted? When the prove the provent of the proven	PEXAS 79701 ad copy of this form is to 10-3-61 Plug Back Same Res P.B.T.D. Tubing Depth Depth Casing Shoe	o be sent)
If well produces of give location of tar fine production COMPLETION I Designate Ty Date Spudded Elevations (DF, RI Perforations HOLI	d Transporter of VICE OIL C l or liquids, nl:s. is commingled DATA yoe of Comple K.3, RT, GR, en	f Casinghead Ga COMPANY Unit J d with that from letion — (X) Date Comp co., Name of P CAS	Sec. Twp. Rge. 30 85 37E n any other lease or pool, Oil Well Gas Well ol. Ready to Prod. TUBING, CASING, AND ING & TUBING SIZE WABLE (Test must be a able for this de	RARTLESVILLE, Is gas actually connect TES give commingling ord New Wel. Workover Total Depth Top Oil/Gas Pay CEMENTING RECO DEPTH: fter recovery of total vorpth or be for full 24 how	MIDIAND, to which approve OKLAHOMA Ted? When the prove the provent of the proven	PREAS 79701 Id copy of this form is to the copy of this form is the copy of t	o be sent)
If well produces of give location of tar of this production COMPLETION I Designate Ty Date Spudded Elevations (DF, RI Perforations	d Transporter of VICE OIL C 1 or liquids, nl:s. is commingled DATA TO COMPLETE TO REQUEST	f Casinghead Ga COMPANY Unit J d with that from letion — (X) Date Comp CAS CAS	Sec. Twp. Rge. 30 85 37E n any other lease or pool, Oil Well Gas Well ol. Ready to Prod. TUBING, CASING, AND ING & TUBING SIZE WABLE (Test must be a able for this de	Address (Give address RARTLESVILLE, Is gas actually connect YES give commingling ord New Wel. Workover Total Depth Top Oil/Gas Pay CEMENTING RECO DEPTH:	MIDIAND, to which approve OKLAHOMA Ted? When the prove the provent of the proven	PREAS 79701 Id copy of this form is to the copy of this form is the copy of t	o be sent) V. Diff. Resty
If well produces of give location of tar of this production COMPLETION I Designate Ty Date Spudded Elevations (DF, RI Perforations HOLI TEST DATA ANOIL WELL	d Transporter of VICE OIL C 1 or liquids, nl:s. is commingled DATA TO COMPLETE TO REQUEST	f Casinghead Ga COMPANY Unit J d with that from letion — (X) Date Comp CAS CAS	Sec. Twp. Rge. 30 85 37E n any other lease or pool, Oil Well Gas Well ol. Ready to Prod. TUBING, CASING, AND ING & TUBING SIZE WABLE (Test must be a able for this de	Address (Give address RARTLESVILLE, Is gas actually connect YES give commingling ord New Wel. Workover Total Depth Top Oil/Gas Pay CEMENTING RECO DEPTH: fter recovery of total vor pth or be for full 24 how Producing Method (Flace)	MIDIAND, to which approve OKLAHOMA Ted? When the prove the provent of the proven	PEXAS 79701 Id copy of this form is to the copy of this form is the cop	o be sent) 'v. Diff. Res'v
If well produces of give location of tar of this production COMPLETION I Designate Ty Date Spudded Elevations (DF, RI Perforations HOLI TEST DATA ANOIL WELL	d Transporter of VICE OIL C 1 or liquids, nl:s. is commingled DATA TO COMPLETE TO REQUEST	f Casinghead Ga COMPANY Unit J d with that from letion — (X) Date Comp CAS CAS	Sec. Twp. Rge. 30 85 37E n any other lease or pool, Oil Well Gas Well oil. Ready to Prod. TUBING, CASING, AND ING & TUBING SIZE WABLE (Test must be a able for this de	RARTLESVILLE, Is gas actually connect TES give commingling ord New Wel. Workover Total Depth Top Oil/Gas Pay CEMENTING RECO DEPTH: fter recovery of total vorpth or be for full 24 how	MIDIAND, to which approve OKLAHOMA Ted? When the prove the provent of the proven	PREAS 79701 Id copy of this form is to the copy of this form is the copy of t	o be sent) 'v. Diff. Res'v
If well produces of give location of tar of this production COMPLETION I Designate Ty Date Spudded Elevations (DF, R) Perforations HOLI TEST DATA AN OIL WELL Date First New Oil	d Transporter of VICE OIL C 1 or liquids, nl:s. is commingled DATA TO COMPLETE TO REQUEST	CAS CAS Casinghead Ga Company Unit J d with that from letion — (X) Date Comp Cas Cas Cas	Sec. Twp. Rge. 30 85 37E n any other lease or pool, Oil Well Gas Well oil. Ready to Prod. TUBING, CASING, AND ING & TUBING SIZE WABLE (Test must be a able for this de	Address (Give address RARTLESVILLE, Is gas actually connect YES give commingling ord New Wel. Workover Total Depth Top Oil/Gas Pay CEMENTING RECO DEPTH: fter recovery of total vor pth or be for full 24 how Producing Method (Flace)	MIDIAND, to which approve OKLAHOMA Ted? When the prove the provent of the proven	PEXAS 79701 Id copy of this form is to the copy of this form is the cop	o be sent) 'v. Diff. Res'v

Date First New Oil Run To Tonks	Date of Test	Producing Method (Flow, pu	np, gas lift, etc.)
Length of Test	Tubing Pressure	Casing Pressure	Choke Size
Actual Prod. During Test	Oil-Bbls.	Water-Bbis.	Gas-MCF

GAS WELL Actual Prod. Test- MCF/D Bbls. Condensate/MMCF Gravity of Condensate Length of Test Tubing Pressure (Shut-in) Casing Pressure (Shut-in) Choke Size Testing Method (pitot, back pr.)

VI. CERTIFICATE OF COMPLIANCE

Ħ

Ш

IV

I hereby certify that the rules and regulations of the Oil Conservation Commission have been complied with and that the information given

bove is true and complete to the best of my knowledge and belief.
Jo mie Wilson
(Signature)
(PARTATER)
(Title)
2-4-71
(Date)

ALL CONCEDIA TION COMMISSION				
	IL CONSERVATION COMMISSION	CONSE	11.	-

1 TITLE.

This form is to be filed in compliance with RULE 1104.

If this is a request for allowable for a newly drilled or deepened well, this form must be accompanied by a tabulation of the deviation tests taken on the well in accordance with RULE 111.

All sections of this form must be filled out completely for allowable on new and recompleted wells.

Fill out only Sections I, II, III, and VI for changes of owner, well name or number, or transporter, or other such change of condition. Separate Forms C-104 must be filed for each pool in multiply

RECEIVE

7. %

• •

FE0 1 100:

MLAPO MOSECULATION CALM.