

Hayes Federal Well # 2

Sheet 3

March 14, 1984

Rig up casing jacks and jack liner hanger out
Pulled 6 jts. of 4-1/2" casing. Shut down.

March 15, 1984

T I H with over shot, jars, BS, D.C. a
to catch fish. TOH skirt on over shot

March 16, 1984

T I hole with 3-1/8" screw in pi
casing collapsed so bad unable
tubing, Takes 120000# to pull
T.A. well.

Hayes Federal Well # 2
February 29, 1984
T I H with 3-7/8" string mill milled to 5386' shut down.

March 1, 1984
Milled T O H put on 3-7/8" swedge T I H swedge to

March 2, 1984
T O H drill collars pulged. T I H w
to 5408', turned on tubing filled tub.
left skirt off bottom of overshot

March 7, 1984
T.I.H. to 5386' with 2-7/8
hole came 17 jts and hur

March 8, 1984
T I H with 4
T.O.H. pick
catch fi
Mar