

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYCOPY TO O. C. C.
SUBMIT IN TRIPLICATE*
(Other instructions
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 02915

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal "C"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Prairie Cisco, South

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 20, T-8-S, R-36-E

12. COUNTY OR PARISH

Roosevelt

13. STATE

N. M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. NAME OF OPERATOR American Petrofina Co. of Texas	
3. ADDRESS OF OPERATOR P. O. Box 1311 Big Spring, TX 79720	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980 ft FNL and FE L, Sec 20, T-8-S, R-36-E, Roosevelt Co., NM	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) + 4124 D.F.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) Plug present producing zone, ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐Perf. & test new zone. ☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- Set cast iron bridge plug at 9550 ⁺ (Top of present casing perf. 9653) and place ten ft cement on top of plug.
- Perforate casing from 8990-9010
- Acidize perforations and test
- Proposed starting date Oct. 2, 1978

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

18. I hereby certify that the foregoing is true and correct

SIGNED J.C. Chapman J.C. Chapman TITLE Asst. Dist. Mgr. of Prod. DATE 9-7-78

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

*See Instructions on Reverse Side

