

H. M. OIL CONS. COMMISSION
P. O. BOX 1500
MOLDS, NEW MEXICO 88240

Form Approved.
Budget Bureau No. 42-R1424

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐
2. NAME OF OPERATOR
American Petroleum Co. of TX
3. ADDRESS OF OPERATOR
Box 1311, Big Spring, TX 79720
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: **1980'N 660'W**
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

☐
☐
☐
☐
☐
☐
☐
☐
☒

5. LEASE

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal "C"

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

South Prairie San Andres

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

21. T-3-S, 2-36-E NEPM

12. COUNTY OR PARISH

Roosevelt

13. STATE

N. M.

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

4126.5 DF

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6-19-81 Spotted 40 ex cement from 5393' to 5366'. Loaded hole with 150 bbls. 9.5 mud. Spotted 40 ex cement plug from 4260' to 4120'.
5-20-81 Ran gauge ring to 4160' & found no plug. Spotted 40 ex cement plug from 4160' to 4120'.
6-22-81 Tagged cement plug at 4162'. Spotted 40 ex cement plug from 361' to 363'.
6-23-81 Tagged plug at 471'. Spotted 40 ex cement plug from 471' to 333'. Set 15 ex cement plug at surface. Set 4 1/2" pipe marker. Well site now ready for inspection.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED **J. A. Gillham** TITLE **Asst. Dist. Mgr.** DATE **February 1, 1982**

APPROVED

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

NOV 1 1982

FOR
JAMES A. GILLHAM
DISTRICT SUPERVISOR

TITLE _____ DATE _____

*See Instructions on Reverse Side

477

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.