

N. M. OIL CONS. COMMISSION
P. O. BOX 1980
HOBBS, NEW MEXICO 88240

Form 9-331
Dec. 1973

Form Approved.
Budget Bureau No. 42-R1424

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐
well well

2. NAME OF OPERATOR
SNB Operating Co.

3. ADDRESS OF OPERATOR
P.O. Box 543 Lovington N M 88260

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1956' SW
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☒
(other)

☐
☐
☐
☐
☐
☐
☐
☐
☐

5. LEASE

NM-058677

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

N M Federal B

9. WELL NO.

2

10. FIELD OR WILDCAT NAME

South Prairie Cisco

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 31 T 26S R 37-E

12. COUNTY OR PARISH

13. STATE

14. API NO.

N M

15. ELEVATIONS (SHOW DF, KDB, AND WD)

4111 GR.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

133/8-427'-400sxs
4/5/8-4282'-1905sxs
7" -9751'- 600 sxs

Perforations
9480'-9486'

1. CIBP @ 9400'-dump 35' cement on top
2. Circulate hole with 10# mud
3. cut and pull from freepoint all recoverable 7" casing
4. Spot 100' cement in and out of stub 100' top plug
5. Spot 50 sxs cement @ 4332-4432 14352-4412 top plug.
6. Cut and pull any 9 5/8 casing if free believe to be circulated
7. Spot 100' cement in and out of stub if pulled
8. Spot 85 sxs @ 477'-377'
9. Spot 10 sxs @ surface
10. Spot 10 sxs @ surface

Install dry hole marker Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED R. Smith TITLE Agent DATE 2-20-90

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

APPROVED
PETER W. CANTER

FEB 28 1990

*See Instructions on Reverse Side

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

RECEIVED
FEB 23 9 01 AM '90
BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

RECEIVED

MAR 2 1990

OCD
MOBBS OFFICE